Submit 3 Copies

State of New Mexico to Appropriate Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OIL C	ONSERVATION	DIVISION	V				1-05
		P.O. Box 2088						
DISTRICT I	S	anta Fe, New Mex	ico 87504-	2088				
P.O. Box 1980, Hobbs, NM 8824	10	and the state of t	100 07 004-2	2000				
DISTRICT II					API NO (essio	ned by OCD on New	. 347-11-3	
P.O. Drawer Dd, Artesia, NM 882	210				30-025-2	4950	/ VVeils)	
DISTRICT III					5. Indicate Ty			
1000 Rio Brazos Rd., Aztec, Nm	B7410				o. moleste (STATE	FEE!	.
							FEE	<u> </u>
					1	& Gas Lease No.		
	SUNDRY NOTICES A	ND PEDODEC ON W	=		26	09		
SUNDRY NOTICES AND REPORTS ON WELLS								
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Nam	e or Unit Agreement	: Name	
			ERMIT"		ELLA			
1. Type of Well:	(FORM C-101) FOR SI	OCH PHOPOSALS.)			_}			
OIL	GAS				İ			
WELL X	WELL OTH	ER			l			
2. Name of Operator					<u> </u>			
CHEVRON	U.S.A. INC.				8. Weil No.			
3. Address of Operator						2		
P.O. BOX 1150 MIDLA	ND, TX 79702 ATTN:	WENDI KINGSTON			9. Pool name			
4. Well Location	_				PLINEBRA	OIL & GAS		
Unit Letter	B : 560'	Feet From The	NORTH	Line and	198	30 Feet From The	EAST	
Section 2		Township 22S		Range	37E	NMPM	LEA	Line
		10. Elevation(Show what	her DF, RKB, RT, G	iR, etc.)				County
<i>/////////////////////////////////////</i>		<i>///</i>	3318'					
	Check Appropriate Box	o Indecate Nature of Noti	ce, Report, or O	ther Data				
	INTENTION TO:		SUBSEQ	UENT RE	PORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL	WORK]	ALTER CASING	Г	7
TEMPORARILY ABANDON	CHANGE PLANS	COMMENC	E DRILLING OPNS.		1	PLUG AND ABA	<u>,</u>	
PULL OR ALTER CASING		CASING T	EST AND CMT JOB	. –	1	I LOG AND ABA	*· L	
OTHER:		OTHER:	RECOMPLI		J			
*************************************		III.	TECOMPLE	E 1 E			X	
12. Describe Proposed or Complet	ted Operations(Clearly state all pertin	ent details, and give no-i	d-4 1 1 1					
esticated date of starting any pr	oposed work) SEE RULE 1103.	And Advance and Blaz bettilleut	dates, including					
MIRU. SE	T CIBP @62 10'W/10' (OMT ON TOP, PERF	F/5420'-583	וחי ארם:	7 DEDEC MA	200 0 41 6		
15% NEF	E HCL. FRAC PERFS W	76 000 GALS LINE	AP GEL 8. 22	4 750 · 5	- FERFS W/.	ZUU GALS		
DILLAMO	0/01 700 70	. 2,000 GAEG FINE	THE GEL & 22	4,/50 Lb	55 16/30 BF	rady SD.		

RIH W/2 3/8" TBG TO 5861'. WELL WORK COMPLETED 10/16/95.

I hereby certify that the information above instruments complete to the best of my knowledge and belief.		
SIGNITURE TECH. ASSISTANT	DATE:	11/2/95
TYPE OR PRINT NAME WENDI KINGSTON	TELEPHONE NO.	(915)687-7826
ORIGINAL SIGNED BY JERRY SEXYON APPROVED BY DISTRICT SUPPRINCIPLE CONDITIONS OF APPROVAL, IF ANY:	DATE	NOV 28 1995