

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**  
**P O. Box 2088**  
**Santa Fe, New Mexico 87504-2088**

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

|  |  |   |
|--|--|---|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORMC-101) FOR SUCH PROPOSALS.)           |  | WELL API NO.<br><b>3002524990</b>   |
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  |  | 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 2. Name of Operator<br><b>EXXON CORPORATION</b>  |  | 6. State Oil & Gas Lease No.<br><b>FEE</b>  |
| 3. Address of Operator<br><b>ATTN: REGULATORY AFFAIRS</b><br><b>P. O. BOX 1600</b><br><b>MIDLAND, TX 79702</b>   |  | 7. Lease Name or Unit Agreement Name<br><b>N G PENROSE</b>  |
| 4. Well Location<br>Unit Letter <b>G</b> : <b>1980</b> Feet From The <b>NORTH</b> Line and <b>1980</b> Feet From The <b>EAST</b> Line<br>Section <b>13</b> Township <b>22S</b> Range <b>37E</b> NMPM <b>LEA</b> County |  | 8. Well No.<br><b>30</b>  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br><b>3334 GR</b>   |  | 9. Pool name or Wildcat<br><b>BLINEBRY OIL</b>  |

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: **ADD BLINEBRY PERFS.** ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**WELL IS PRESENTLY DOWN HOLE COMMINGLED FROM THE BLINEBRY, S. BRUNSON DRKD/ABO AND WANTZ GW. INTENT IS TO SET CIBP'S AT 5909' AND 6300' TO ISOLATE DRKD/ABO AND GRANITE WASH. ADD BLINEBRY PERFS. 5441'-5528', FRAC. WITH APPROX. 18600 GAL. + 66000 # SD. TEST BLINEBRY BEFORE MAKING DECISION TO REMOVE CIBP'S AND RECOMMINGLE WITH DRKD/ABO AND GRANITE WASH.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Alex M. Correa* TITLE **Sr. Regulatory Specialist** DATE **08/19/93**  
TYPE OR PRINT NAME **Alex M. Correa** (915) 688-6782 TELEPHONE NO.

(This space for State Use)

**ORIGINAL SIGNED BY JERRY SEXTON**  
**DISTRICT I SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **AUG 24 1993**

CONDITIONS OF APPROVAL, IF ANY: