	ENERGY AND MINISPALS DEPARTMENT	
	OIL CONSERVATION DIVISIO	
	DISTRIBUTION P. O. BOX 2088	Form C-103
	SANTA FE, NEW MEXICO 87501	Revised 10-1-7
	FILE	5a. Indicate Type of Lease
٠,	U.S.G.S.	State Fee X
	LAND OFFICE	
	OPERATOR	5. State Oti & Gas Lease No.
	SUNDRY NOTICES AND REPORTS ON WELLS	
	ON X GAS OTHER-	7. Unit Agreement Name
	_ Name of Operator	8. Farm or Lease Lame
	Gulf Oil Corporation	H. T. Mattern (NCT-D)
- =	), Address of Operator	9. Well No.
	P. O. Box 670, Hobbs, NM 88240	11
<u> </u>	4. Location of Well	10. Field and Pool, or Wildcat
i		Hlinebry Tubb Drinkard
1	WHIT LETTER F . 1980 FEET FROM THE NORTH LINE AND 1650 FEET FROM	
	THE West LINE, SECTION 6 TOWNSHIP 22S MANGE 37E HMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
-		Lea
	3457' GL	
	Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
	NOTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
		_
	PERFORM REMEDIAL WORK	ALTERING CASING
_	TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDOHMENT
	PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JOB	•
-	OTHER DHC Blinebry, Tub	b, Drinkard(R-7238)
	OTHER	
:	17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.	estimated date of starting any propose
i i	POH with production equipment. Knock out CIBP at 6000' and clean Acidize with 5000 gals 15% NEFE HCL, (132) RCNB's, 2200# rock salt acid. ISIP 750#, 15 min vac. GIH with tubing, perf sub, SN to 66	, 1100# benzoic 39'. GIH with
:	pump and rods, space out rods and hung on. Complete after DHC Bli Drinkard 5-17-83.	nebry, Tubb,
	·	

Area Engineer

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

5-26-83

MAY 3 1 1983

MAY 27 1983 HOBBS OFFICE