OGY AND MILLIPALS DEPARTMENT		TION DIVISIO	Ravised 10-1-70
DIST 10 UT 10H	P, O, DC		
5ANTA PV 7 IL P	SANTA FU, NUV	V MEXICO 87501	
U 8,41.0.			
TRANSPORTER OIL		R ALLOWABLE ND	
GAR OPERATOR PAGRATION OPEICE		PORT OIL AND NATURAL GA	S
Gulf Oil Corporati	on		
Address D. O. Borr 670 Hoh	bs. NM 88240		
P. O. Box 670, Hot	box)	Other (Please explain)	
new Well	Change in Transporter of: Ott Dry Go		
Necompletion A Change In Ownership	Casinghead Gas Conde		
If change of ownership give nam and address of previous owner	c		
DESCRIPTION OF WELL AN	D LEASE		
Lease Nona	Well No. Pool Name, Including F		
H. T. Mattern (NCT	-D) 12 Blinebry	-1114 State, P	ederal or Fee Fee
Unit Letter K ; 2	130 Feet From The South Lir	is and <u>1860</u> Feet F	rom TheWest
Line of Section 6	Township 22S Range	37E , NMPM, LE	a County
LICCONTRIANON OF TRANSPO	ORTER OF OIL AND NATURAL GA	S	
None of Authorized Transporter of	Cil [X] or Condensate	Address (Give address to which a	pproved copy of this form is to be senij
Texas-New Mexico Pipeline		Box 1510, Midland, Address (Give address to which o	TX 79701 pproved copy of this form is to be sent)
Warren Petroleum Corp.		Box 1589, Tulsa, C	
If well produces all or liquids, give location of tanks.	Unit Sec. Twp. Rge. A 1 22S 37E	is gas actually connected?	When 8-2-79
	A L 22S 3/E with that from any other lease or pool,	give commingling order number:	
COMPLETION DATA	Oil Well Gas Well	New Well Workover Deeper	
Designate Type of Comple	1 XX	↓ ↓ ↓ ↓ ↓ ↓ ↓	XX
Dute SXXXXI	Date Compl. Ready to Prod.	Total Depth	P.B.T.D.
8-1-82 1 levations (DF, RAB, RT, GR, etc.	8-8-82 , "ame of Producing Formation	6800 ¹ Top Oil/Gas Pay	6100' Tubing Depth
3454' GL	Blinebry	5478'	5724 ¹ Depth Casing Shoe
5478'-5704'			
		CEMENTING RECORD	SACKS CEMENT
HOLE SIZE	CASING & TUBING SIZE	DEPTH SET	SAUNS CEMENT
No New Casing			
TEST DATA AND REQUEST	FOR ALLOWABLE (Test must be a)	l fier recovery of social volume of load	l oil and must be equal to or exceed top allow
OIL WELL	able for this de	pth or be for full 24 hours) Producing Method (Flow, pump, se	
Cute First New Off Hun To Tanks 8-8-82	8-11-82	Pumping	
·	Tubing Preseure	Casing Pressure	Choke Size
24 hrs Actual Prod. During Test	<u>40#</u> оп-выя.	40#	Gat-MCF
118	78	40	122
CAS WELT			
GAS WELL Actual Fred. Tool-MCF/D	Length of Teel	Bbls. Condensate/NUMCF	Gravity of Condensate
leating kiethod (pitor, back pr.)	Tubing Presews (shut-in)	Cosing Pressure (Shut-in)	Chok• Six•
CERTIFICATE OF COMPLIA	NCE	OIL CONSER	VATION DIVISION
	desculations of the Oll Crosservation	APPROVED AUG18	<u>1982</u>
I hereby certify that the rules and regulations of the Olt Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		ORIGINAL SIGNED BY	
		DYJERRY SEXTON	
			12C.C.
~ /	`		la corolizora ulto mili e 1942
ROL) to o	This form is to be filed	in compliance with MULE 1104. Nowable for a newly drilled or deepened
R.D.F.	ite	This form is to be filed If this is a request for a well, this form must be acco tests taken on the well in a	liowable for a newly drilled or despended inpanied by a tabulation of the deviation coordance with AUL& 111.
Area Engir	neer	This form is to be filed If this is a request for a well, this form must be acco tests taken on the well in a All acctions of this form	Howable for a newly drilled or deepened mpanied by a tabulation of the deviation coordance with AULE 111. I must be filled out completely for allow-
Area Engir		This form is to be filed If this is a request for a well, this form must be acco tests taken on the well in a All sections of this form able on new and recompletes	Howable for a newly drilled or despended impanied by a tabulation of the deviation coordance with NULE 111. I must be filled out completely for allow- 3 wells. I to the and VI for changes of owner.
Area Engir (8-12-82	neer	This form is to be filed If this is a request for a well, this form must be acco- tests taken on the well in a All sections of this form able on new and recompleted Fill out only Sections well name or number, or trans	Howable for a newly drilled or despended mpanied by a tabulation of the deviation coordance with NULE 111. I must be filled out completely for allow- d wells.

RECEIVED

AUG 1 3 1982

O.C.D. HOSSS OFFICE

ç