C.E. File No. \_\_\_\_\_A-417E

State of New Mexico Enc. gy, Minerals and Natural Resources Depa. ...nent

Submit to Appropriate District Office State Lease—4 copies Fee Lease—3 copies

DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240

DISTRICT # P.O. Drawer DD, Arteela, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

1 Miles S of EUNICE

## OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL LOCATION AND ACREAGE DEDICATION PLAT All distances must be from the outer boundaries of the Section.

														T		
Operator Exxon Corporation									Lease NEW MEXICO "S" STA					Well No.		
								Range			1/1/15	County		<del></del>		
Unit 1	Letter F	Secti	on 2		lowns	225		Kunge	37E		N	мРм		LEA		
Actu	al Foota	ge Loc	catio	n of	Well:								***			
	2160			om tl		N	line a		800	feet	from	the	W	line.	<b>A</b>	
Grour	nd level	Elev.	Pro	ducin	g Format	ion		Pool				_		Dedicated	•	
	3383 RKB BLINEBRY							BLINEBRY OIL & GAS				5		40	Acres	
3.	unitization, force—pooling, etc.?															
	Yes No if answer is "yes", type of consolidation															
	this form if necessary)															
	No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced—pooling, or otherwise) or until a non-standard unit, eliminating such interest, has been approved by the Division.															
							-						OPERATOR CERTIFICATION			
			D	-		С		В	1		A	]	-	certify that th		
			1	1		1		_	1 }			1 1		rein is true and bi nowledge and bi	complete to the	
			-						i			1		A		
			į						 			Siç	nature	Alman		
			! !						i			1 1 1	inted Nag	ne		
			i	2160					1				sition	J. Johnson	on	
1 L _			<u> </u>	~		T. T. T.			 			A	dminist	rative Sp	ecialist	
			E			F		G	i		H	1 1		Exxon Co		
			i			3			1			P.	0. Box 10	600-Midland	, Tx79702	
11			1						] 			Do	ite 5-	30-90		
				ł	φ <sup>28</sup>				1				SURVE'	YOR CERT	TFICATION	
		1800							i					rtilly that the w		
	•		i	È								41			otted from field	
			L			K		J			1			ctual surveys m		
			_	!					1					supervision, and		
			i	i i					i				In true and Impaledge	i correct to the and belief.	Best or my	
			,	į					1			Do	te Surve	wed		
				: 			1		i					4/15/76		
				İ					1.			Pr	gnature ë ofessiona	k Seal of I Surveyor		
11-			- <u>-</u>	<u></u>		N					P	]	•			
			<b>•</b>	İ		••		_	!				•			
				1			]		1.				•			
				ļ			1.		1					•		
				1					i		÷			•		
				į					1							
				ļ					<u> </u>			┙┕		<u> </u>		
				<del></del>							<del></del>	ع ا <sup>د</sup> ٰ	ertificate	NO.		
1 6	330 6	60 99	10 13	320 1	650 1980	2310 2	840 20	00 1500	1000	50	)U	<u> </u>				

\_\_\_\_, New Mexico.