

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells) 30-025-25305
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.		6. State Oil & Gas Lease No. N/A
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS		7. Lease Name or Unit Agreement Name R.E. COLE (NCT-A)
4. Well Location Unit Letter G : 1980 Feet From Th NORTH Line and 1980 Feet From The EAST Line Section 16 Township 22S Range 37E NMPM LEA County		8. Well No. 16
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3407 GE		9. Pool name or Wildcat BLINEBRY

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: PERF,ACDZ AND FRAC <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU,POOH WITH PRODUCTION EQUIPMENT.
ACDZ PERFS AT 5863-58-959 WITH 2000 GALS. OF 15% NEFE.
PERFORATE AT 5424-5797 WITH 4" GUNS AND 26 HOLES.
ACIDIZE PERFS AT 5424-5797 WITH 4000 GALS OF 15% NEFE.SWAB BACK ACID.
FRAC PERFS 5424-5797 WITH 88,000 GALS OF 40# XL GEL AND 127,000 LBS. OF 20/40 SAND.
BAIL OUT SAND TO 5746'. TIH WITH TBG. AND RODS. EOT AT 5948'.
RIG DOWN MOVE OUT ON 4-8-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE: 4/9/92

TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO (915)687-7812

APPROVED BY JERRY SEXTON TITLE SUPERVISOR DATE APR 12 '92
CONDITIONS OF APPROVAL, IF ANY: