

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No.</p>
<p>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>Name of Operator <b>Gulf Oil Corporation</b></p> <p>Address of Operator <b>Box 670 Hobbs, N.M.</b></p> <p>Location of Well UNIT LETTER <b>L</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>510</b> FEET FROM THE <b>West</b> LINE, SECTION <b>29</b> TOWNSHIP <b>22-S</b> RANGE <b>38-E</b> NMPM.</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name <b>Evelyn Lineberry</b></p> <p>9. Well No. <b>3</b></p> <p>10. Field and Pool, or Wildcat <b>Wantz Granite Wash</b></p>
<p>11. Elevation (Show whether DF, RT, GR, etc.) <b>3386' GL</b></p>		<p>12. County <b>Lea</b></p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/> <b>TA Wantz Granite Wash and complete in Drinkard.</b></p>		<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>	
--	--	---	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7730' TD 7684' PB

Pull Producing equipment. Set packer at 7200' with WL plug in place. Temporarily abandoning Wantz Granite Wash perfs 7241' to 7307'. Test packer & casing to 2500#. Spot 15% HCL NE acid from 7163' to 6850'. Perforate 7" casing with 2, 1/2" JHPF at 6932-34, 6968-70, 7016-18, 7088-90, and 7161-63'. Treat new perfs with additional 5000 gallons 15% HCL NE slick acid. Flush with slick 8.6# brine water. Frac with 36,000 gallons 8.6# gelled brine & sand. Flush with 2,200 gallons slick 8.6# brine water. swabb and clean up and test. Run Production equipment, place well on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <b>O. F. Berlin</b>	TITLE <b>Area Engineer</b>	DATE <b>May 20, 1977</b>
ORIG. SIGNED BY <b>Jerry Sexton</b>	TITLE <b>Dist 1, Supv.</b>	DATE <b>MAY 23 1977</b>
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY		

RECEIVED

DEC 21 1977

U.S. AIR FORCE COMM.