

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Marathon Oil Company 3. Address of Operator P.O. Box 2409 Hobbs, NM 88240 4. Location of Well UNIT LETTER <u>D</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3369 RKB	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> 5. State Oil & Gas Lease No. 7. Unit Agreement Name 8. Farm or Lease Name Walter Lynch 9. Well No. 7 10. Field and Pool, or Wildcat <u>Drinkard</u> 12. County Lea
---	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐ OTHER TA Wantz Granite Wash Zone ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-14-80 Killed Drinkard Zone with 2% KCl water. Installed BOPs. Pulled out of hole with 2 1/16" tubing.
- 4-15-80 Killed Drinkard Zone with 2% KCl water. Went in hole with 7" Baker retrievable bridge plug on 2 1/16" tubing. Set bridge plug at 6498'. Pulled out of hole with retrieving tool on 2 1/16" tubing. Went into hole with seating nipple on 204 jts 2 1/16" tubing. Removed BOPs. Installed wellhead.

Note: Well No. 7 is now a single Drinkard Zone completion producing from 6324' - 6363'.  
The Wantz Granite Wash Zone is temporarily abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Patrick Burton TITLE Production Engineer DATE 6-24-80

APPROVED BY Jerry Sexton TITLE Dist. J. Supv. DATE JUN 27 1980  
CONDITIONS OF APPROVAL, IF ANY: