

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name Walter Lynch
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	9. Well No. 7
4. Location of Well UNIT LETTER <u>D</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>22-S</u> RANGE <u>37-D</u> N.M.P.M.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3369 RKB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Tubing leak in long string</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6-22-79 Rigged up pulling unit. Pulled out of hole with pump, gas anchor, and rods from long string (Granite Wash).
- 6-23-79 Rigged up Jarrel Wireline. Set check valve in Otis seating nipple of long string. Killed Drinkard zone with lease oil. Removed dual tubing hanger. Installed BOPs.
- 6-26-79 POH with Otis J-Latch and short string (Drinkard). Jarred on Otis R-H packer.
- 6-27-79 Jarred on Otis R-H packer -- would not release. Cut tubing at 7059' with chemical cutter. POH with Otis R-H packer, and Otis dual anchor on 2 3/8" tubing.
- 6-28-79 Caught top of fish with overshot and grapple. Could not release 7" Baker Lok-set packer at 7302'. Cut tubing at 7247' with chemical cutter.
- 6-29-79 Pulled out of hole with 2 3/8" tubing and cutoff. Went in hole with bumper sub, drill collars, jars, and grapple on 2 3/8" tubing. Jarred on packer. Slipped off fish and then was unable to catch fish. Pulled out of hole with overshot, jars, bumper sub, drill collars on 2 3/8" tubing.
- 6-30-79 RIH with short string. Removed BOPs. Installed wellhead. Producing Drinkard to battery.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Patricia Burton TITLE Production Engineer DATE 6-24-80

APPROVED BY Jerry Serna TITLE DATE JUN 27 1980

CONDITIONS OF APPROVAL, IF ANY: