Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural Re	esources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		Well API NO. 30-025-25518
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. V-2274
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
			7. Lease Name or Unit Agreement Name
1. Type of Well: Oil CAS WILL XX WELL	OTHER		RL
2. Name of Operator C. W. Trainer			8. Well No.
3. Address of Operator P. O. Box 755, Hobbs	s, NM 88241		9. Pool name or Wildcat Wildcat
	30 Feet From The South		
Section 16	Township 23S Ras	nge <u>33</u> E DF, RKB, RT, GR, etc.)	NMPM Lea County
	Appropriate Box to Indicate N		-
NOTICE OF INTENTION TO: SUE			
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING		CASING TEST AND CE	
OTHER:		OTHER: Daily	Operations Report
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	tions (Clearly state all persinent details, and	d give pertinent dates, inclua	ling estimated date of starting any proposed

7/2/92	Move in and rig up Halliburton Services. Lay flowline to pit
	from wellhead. Start pumping nitrogen to displace fluid from wellbore. Unload heavy mud and water from wellbore. Circulate
	hole completely dry from bottom of tubing at 11,605. Shut down
	and bleed off nitrogen. Tested tubing and casing to 4200#. Rig down Halliburton and shut down.

hereby certify that the information above is true and complete to the best of KINATURE	me Agent	DATE 7/6/92
YPE OR PRINT NAME		TELEPHONE NO.
China spaces for State Use) ORIGINAL SIGNED BY JERRY DISTRICT I SUPERVISO		JUL 0 7 '92
	TILE	