

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name Lou Worthan
3. Address of Operator P.O. Box 2409 Hobbs, New Mexico 88240	9. Well No. 18
4. Location of Well UNIT LETTER <u>H</u> <u>1905</u> FEET FROM THE <u>North</u> LINE AND <u>860</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> RMPM.	10. Field and Pool, or Wildcat Wantz Granite Wash, Tubb
15. Elevation (Show whether DF, RT, GR, etc.) KB 3367'; GR 3355'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>pipe bradenhead connections to the surface.</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Dug out well cellar to expose casing bradenhead outlets.
2. Installed 1" piping from 2" valve on each bradenhead outlet to a point above ground level. Installed 1" valve on upper end of piping.
3. Conducted Bradenhead Pressure Survey.
4. Piping arrangement, open position of lower valve and closed position of valve above ground level, inspected and approved by NMOC Deputy Oil & Gas Inspector, David Catanach.

Bradenhead Size

9 5/8"

Bradenhead  
Valve Location

Southeast side of Wellhead

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Searns TITLE Engineering Technician DATE 5-18-83

APPROVED BY David Catanach TITLE OIL & GAS INSPECTOR DATE MAY 23 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAY 20 1983  
O.C.D.  
HOBBS OFFICE