

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**

Form C-103  
Revised 1-1-89

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)

30-025-25906

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

N/A

7. Lease Name or Unit Agreement Name

HUGH

8. Well No.

13

9. Pool name or Wildcat

WANTZ(ABO)

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

GAS

WELL ☐

WELL ☒

OTHER

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location

Unit Letter

A

710

Feet From The

NORTH

Line and

330

Feet From The

EAST

Line

Section

14

Township

22S

Range

37E

NMPM

LEA

County

10. Elevation(Show whether DF, RKB, RT, GR, etc.)

3338' GL

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTER CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABAN. ☐

CASING TEST AND CMT JOB ☐

OTHER: PLUG BACK, NEW ZONE ☒

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 04/14/94. MIRU, ND WH, NU BOP. SET CIBP @7350', CIRC HOLE W/3% KCL WTR.  
RUN GAMMA RAY/CCL F/7150'-6500'. PERF F/6606'-7045' AT 2 JHPF. CAP CIBP W/10' CMT.  
ACDZ PERFS W/200 GALS OF 15% HCL. SWAB WELL. FLOW WELL.  
ACDZ FRAC W/8,400 GALS 28%, 27,000 GALS 40# GEL, 6,000 GALS 15% ACID.  
ND BOP, NU TREE. SWAB TBG DN TO 4500'. LEAVE WELL FLOWING TO TANK.  
TURN WELL OVER TO PRODUCTION 04/22/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Wendi Kingston*

TITLE

TECH. ASSISTANT

DATE:

04/28/94

TYPE OR PRINT NAME

WENDI KINGSTON

TELEPHONE NO. (915)687-7436

APPROVED BY

ORIGINAL TITLE

DATE

MAY 02 1994

CONDITIONS OF APPROVAL, IF ANY: