we. or cortts acceives	T	
POITTHEUTION		
BANTA PE	1	
FILZ	1	
V.S.G.S.	T	
LAND OFFICE	1	
PERATOR	+	1

Form C-1

OIL CONSERVATION DIV P. O. BOX 2088 SANTA FE, NEW MEXICO 87501 Revised Su. Indicate Type of Lease State X 5. State Oll & Gas Lease No. LG-286 SUNDRY NOTICES AND REPORTS ON WELLS THE TOTAL FOR MET AND THE COUNTY OF THE COUN 7. Unit Agreement Name WELL X 2. Name of Operator 8. Farm or Lease Name Amoco Production Company State GA 3. Address of Operator 9. Well No. P. O. Box 68, Hobbs, New Mexico 88240 4. Location of Well 10. Field and Pool, or Wildest 1980 South 1980 Wildcat Strawn 23-S 34-E 15. Elovation (Show whether DF, RT, GR, etc.) Lea Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: FORM REMEDIAL WORK COMMENCE DRILLING OPHS. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any p On 8-16-82 moved in service unit. Pulled packer and tubing. Ran tubing to 11805' and spotted an 80 sack class H cement plug. Pulled tubing to 10000'. WOC. Tagged cement at 11026 and pulled tubing. Cut 9-5/8" casing at 4676' and pulled. Ran tubing to 5164' and spotted 75 sacks of class H cement. WOC. Ran tubing to 5164' and did not tag cement. Loaded casing with 36 BW and spotted 80 sacks class H cement. WOC. Tagged cement at 4920'. Ran tubing to 4731' and spotted 75 sacks of class H cement. WOC. Tagged cement at 4610'. Pulled tubing to 1905'. Set 150 sack class H cement plug. Pulled tubing to 784' and spotted a 75 sack class H cement plug. Spotted a 15 sack surface plug. Welded on cap and erected PXA marker. 0+4-NMOCD,H 1-H0U 1-W. Stafford, HOU 1-DMF ld. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Assist. Admin. Analyst 9-15-82