form 3160-5 June 1990)	UNITED S DEPARTMENT OF	THE INTERIOR	N.M. Oil Cons. P.O. Box 1980	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LAND		Hobbs, NM 8824	15. Lease Designation and Serial No. LC-030132 B
Do not use this form Use	SUNDRY NOTICES AND n for proposals to drill or to PAPPLICATION FOR PE	o deepen or reentry to	o a different reservoir.	6. If Indian, Allottee or Tribe Name
<u></u>	SUBMIT IN TH	RIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Weit Oil Gas Oil Weit Other 2. Name of Operator SDX Resources, Inc. 3. Address and Telephone No. PO Box 5061, Midland, TX 79704 PO Box 5061, Midland, TX 79704 915/685-1761				8. Weil Name and No. Closson B #22
				9. API Well No.
				30-025-26041
				10. Field and Pool, or Exploratory Area Jalmat Yates
4. Location of Well (Footage, 1980' FSL, 1980' FE Unit J, Sec. 30, T22S)		11. County or Parish, State Lea Co., NM
12. CHECK A	PPROPRIATE BOX(s) TO I	NDICATE NATURE OI	NOTICE, REPORT, C	L
			TYPE OF ACTION	
		Abandonment		Change of Plans
Notice of	Intent	Recompletion		New Construction
	ent Report	Plugging Back		Non-Routine Fracturing
£		Casing Repair		Water Shut-Off
Final Abandonment Notice		Altering Casing		Conversion to Injection
		5 3 0 4		
12 Describe Description of C	ompleted Operations (Clearly state all p subsurface locations and measured an	ertinet details, and give pertinen	n to production. t dates, including estimated date refers and zones pertinent to this	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
13. Describe Proposed or Ca directionally drilled, give	ompleted Operations (Clearly state all p subsurface locations and measured an bg & return to production.	ertinet details, and give pertinen	t dates, including estimated date	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is
13. Describe Proposed or Co directionally drilled, give	subsurface locations and measured an	ertinet details, and give pertinen	t dates, including estimated date	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is
13. Describe Proposed or Co directionally drilled, give	subsurface locations and measured an	ertinet details, and give pertinen	t dates, including estimated date orders and zones pertinent to this ACCEPTED F MAR 1	(tots: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
 13. Describe Proposed or Co directionally drilled, give 3/1 - 5/98 Repair to 	subsurface locations and measured an bg & return to production.	ertinet details, and give pertinen d true vertical depths for all mar	t dates, including estimated date oders and zones pertinent to this ACCEPTED F MAR 1 SGD 1 C COUPLA	(tots: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
 13. Describe Proposed or Cr directionally drilled, give 3/1 - 5/98 Repair to 14. I hereby centify that the particular sectors of the particular sec	subsurface locations and measured an bg & return to production.	ertinet details, and give pertinen d true vertical depths for all mar	t dates, including estimated date oders and zones pertinent to this ACCEPTED F MAR 1 SGD 1 C COUPLA	(tots: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
 13. Describe Proposed or Cr directionally drilled, give 3/1 - 5/98 Repair to 3/1 - 5/98 Repair to 14. I hereby pertify that the is Signed 	subsurface locations and measured an bg & return to production.	ertinet details, and give pertinen d true vertical depths for all mar	t dates, including estimated date oders and zones pertinent to this ACCEPTED F MAR 1 SGD 1 C COUPLA	(tots: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*



•