Office District I 1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Energy, Miner	als and Natu	ral Resources		Revi	sed March 25, 1999	
1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	OIL CONS					Sca March 25, 1777	
District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	OIL CONS			WELL AP	'1 NO. 30-025-260<u>51</u>		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	District II OIL CONSERVATION DIVISION				5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV		0 South Pac		STATE FEE			
District IV	San	ta Fe, NM 8	7505				
2040 South Pacheco, Santa Fe, NM 87505				6. State O	oil & Gas Lease No	0.	
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPERTIES OF THE PROPOSALS.)	CES AND REPOR POSALS TO DRILL OF ICATION FOR PERMI	TO DEEPEN (OR PLUG BACK TO A	7. Lease I	Name or Unit Agre	eement Name:	
1. Type of Well:				MARK			
	Other			8. Well N	Io.:		
2. Name of Operator				11			
Chevron U.S.A. Inc.					ame or Wildcat		
3. Address of Operator P.O. Box 1150, Midland, TX 79702				1	BLINEBRY OIL & GAS (PRO GAS)		
4. Well Location	13104						
_	430 feet from	m tha NY	KIH line and	960	feet from the	EAST line	
Unit Letter	430 Feet If O	m theNO	ine and				
Section 3	Townsh	ip 22 S	Range 37E	NMPM	Count	y LEA	
	10. Elevation (S		DR, RKB, RT, GR, (etc.) 			
11 Check	Appropriate Box	to Indicate	Nature of Notice	Report, o	or Other Data		
NOTICE OF IN		to marca	SU	RSEQUE	NT REPORT	OF:	
		NDON \square	REMEDIAL WORK			RING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABA	MDON	HEMEDIAL WORK	•	L		
TEMPORARILY ABANDON	CHANGE PLAN	s 🗆	COMMENCE DRIL	LING OPNS.		AND IDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D	. 🗆		
OTHER: ADD PERFS; DHC		x	OTHER:				
	eted Operations (Cla	arly state all	pertinent details, and	give pertine	nt dates, including	estimated date	
12. Describe Proposed or Comple of starting any proposed work or recompilation.). SEE RULE 1103	. For Multiple	e Completions: Atta	ch wellbore o	liagram of propose	ed completion	
of starting any proposed work). SEE RULE 1103 343'-5494'; PRESS ETRIEVE OR FUSE 1 745 RONB'S. RU	For Multiple TST TO 30	e Completions: Attached PSI. DRILL CMT BELOW 7223'. PE	to top of:	fiagram of propose FISH @ 6530'. 926' W/4 JHPF.	ed completion	
of starting any proposed work or recompilation. POH W/PROD EQPT. SQZ 53 MILL OVER STUCK PKR & RI ACZ W/15,000 GALS 15% &). SEE RULE 1103 343'-5494'; PRESS ETRIEVE OR FUSH 1 745 RCNB'S. RII GAS & WANTZ; ABO.	For Multiple TST TO 300 CONNECLE TO	PSI. DRILL CMT BELOW 7223'. PE 7230'. GIH W/PMF	TO TOP OF TOP SALE TO TOP OF T	FISH @ 6530'. 926' W/4 JHPF. RETURN WELL TO DATE _ Telephone No.	12/14/99	
of starting any proposed work or recompilation. POH W/PROD EQPT. SQZ 53 MILL OVER STOCK PKR & RI ACZ W/15,000 GALS 15% & PRODUCTION IN BLINEBRY (SIGNATURE J. K. RIPLEY Type or print name J. K. RIPLEY). SEE RULE 1103 343'-5494'; PRESS ETRIEVE OR FUSH 1 745 RCNB'S. RII GAS & WANTZ; ABO.	TST TO 300 DOWNHOLE TO HW/TBG TO TITE	PSI. DRILL CMT BELOW 7223'. PE 7230'. GIH W/PMP	TO TOP OF TOP SALE TO TOP OF T	FISH @ 6530'. 926' W/4 JHPF. RETURN WELL TO	12/14/99	