

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3D-D25-26545
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dual (Oil & Gas)	7. Lease Name or Unit Agreement Name Langley Griffin
2. Name of Operator Anadarko Petroleum Corporation	8. Well No. 1
3. Address of Operator P.O. Box 806 Eunice, NM 88231	9. Pool name or Wildcat Langley Strawn
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 28 Township 22S Range 36E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3508 RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRUPU TOH w/ rods, pump, short side tbg (Strawn) & long side tbg (Devonian)
2. Set RBP @ 9400', spot 10' sand on plug.
3. Run cement retainer & set @ 9320' & squeeze existing strawn perfs w/150 SX H.
4. Drill out & test cement squeeze 1000 PSI.
5. TOH w/ RBP.
6. Perforate upper Strawn 9024'-9270'.
7. Acidize & swab test new perforations.
8. Re-run Devonian tbg, Strawn tbg, pump, and rods.
9. Conduct production test.
10. Run PKR. leakage test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Rick L. Langley* TITLE **Field Foreman** DATE **11-22-93**
TYPE OR PRINT NAME **Rick L. Langley** TELEPHONE NO. **394-3184**

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 24 1993

mp