
Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IP ANY:

State of New Mexico Energy, Minerals and Natural Resources Department



AMENDED-	_
Davies d 1 4 90	

District Office				
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	
Santa Fe. New Mexico 87504-2088		30-025-26723 5. Indicate Type of Lease		
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III			STATE FEE X	
1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOT	ICES AND REPORTS ON WELL	LS		
DIFFERENT RESE	OPOSALS TO DRILL OR TO DEEPEN (RVOIR. USE "APPLICATION FOR PER 2-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A IMIT"	7. Lease Name or Unit Agreement Name GRIZZELL	
1. Type of Well: OHL X WELL X	OTHER			
2. Name of Operator			8. Well No.	
Shell Western E&P Inc. 3. Address of Operator	(WCK 4465	7	9. Pool name or Wildcat	
P.O. Box 576 Houston, T.		<i>'</i>	PADDOCK	
4. Well Location Unit Letter _ ! _ 15	940 Feet From The SOUTH	Line and	380 Feet From The EAST Line	
Section 8	Township 318 Rat	nge 37E	NMPM LEA County	
	10. Elevation (Show whether I			
	////// 3405.7' GR			
	Appropriate Box to Indicate N			
NOTICE OF IN	TENTION TO:	Sut	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	IG OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND C			BOL THAMES	
OTHER:		OTHER: PB & REC	COMP	
work) SEE RULE 1103. 7-14 TO 7-22-93: POH W/PROD EQMT. CO TO TOMMED ABY CIBP. RAN CCL/G	rations (Clearly state all pertinent details, and 7000' W/BIT & SCRPR, POH. S GR STRIP LOG. PERF PADDOCK NE 20% HCL. MADE FOUR SWI	SET CIBP @ 5335'. 5292' – 5321' (1	SPF). ACD PERFS	
I hereby certify that the information above is SIGNATURE			R – ASSET ADMIN. _{DATE} <u>8/09/93</u> TELEPHONE NO. 713/544–379	
(This space for State Use) ORIGINAL	SIGNED BY JERRY SEXTON		0.4.4000	
DIS	STRICT I SUPERVISOR	п.е	DASEP 0.1 1993	

RECEIVED

AUG 8 0 1993

OFFICE