

CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

34. Indicate Type of Lease	State ☒ Fee ☐
35. Lease No. & Gas Lease No.	L-4523

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR NOTICES TO WELLS OR TO REPORTS ON WELLS TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR TO REPORT ON WELLS TO A DIFFERENT RESERVOIR.

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER PXA	7. Unit Agreement No.
2. Name of Operator Amoco Production Company	8. Form or Lease Name State IK
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 10 TOWNSHIP 23-S RANGE 33-E	10. Field and Pool, or District Brininstool Bone S.
11. Elevation (Show whether OF, RT, CR, etc.) 3590.6' GL	12. County Lea

13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Progress or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pro-
work) SEE RULE 1163.

Moved in service unit 3-2-83 and laid down rods and pump. Load well with 100 BW. Released tubing anchor and load hole with 400 bbls brine water. Pulled tubing and tubing anchor. Ran 7-5/8" cast iron bridge plug and set at 9590'. Pumped 100 BBL brine gel. Displaced hole with 305 bbl brine gel. Spotted 25 sx class H cement plug to 9472'. Pulled tubing to 7050' and spotted 25 sx class H cement plug to 6950'. Pulled tubing to 5062' and spotted 25 sx class H cement plug to 4940'. Pulled tubing to 869' and spotted cement plug from 869'-747' with 25 sx class H cement. Cut off wellhead and spotted 20 sx class H cement sur plug. Installed PXA marker and Moved out service unit 3-9-83.

0+4-NMOCD,H 1-HOU 1-W. Stafford, HOU 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Kashim Serrano TITLE Assist. Admin. Analyst DATE 3-16-83
 Approved by C.R. [Signature] TITLE OIL & GAS INSPECTOR DATE JUN 29 1983
 CONDITIONS OF APPROVAL, IF ANY:

REC-110

MAR 23 1991

Q-1
HCBES OFFICE