

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-27200
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. Maddox 000001
7. Lease Name or Unit Agreement Name Maddox
8. Well No. 1
9. Pool name or Wildcat NE Antelope Lea (Group 10) Ridge BS
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3357' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER
2. Name of Operator Mid-America Petroleum, Inc.
3. Address of Operator P. O. Box 3120, Midland, Texas 79702
4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>23-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3357' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Procedure to plug and abandon the Maddox #1.

1. Set CIBP @ 8500'. Dump 35' of cmt. on top of CIBP.
2. Circulate well with 9.5#/gal mud-laden fluid.
3. Set 100' (20 sx) cmt plug from 5584'-5484'.
4. Set 100' (20 sx) cmt plug from 3914'-3814'.
5. Set 100' (20 sx) cmt plug from 1869'-1769'.
6. Set 100' (20 sx) cmt plug from 100' to surface.
7. Cut off wellheads, weld on cap and steel marker.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

B. I. Dippel, Jr.

TITLE

Agent

DATE 12-16-93

TYPE OR PRINT NAME

B. I. Dippel, Jr.

TELEPHONE NO. (915) 684-7005

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

DEC 21 1993

CONDITIONS OF APPROVAL, IF ANY:

Well Equipment Schematic

Lease: Maddox Well: 1 Field: Antelope Ridge

Unit Letter L Location: 1980 feet F S L & 660 feet F W L, Section 12,
T-23-S, R-34-E Block _____, _____ Survey, Lea County, Texas New Mexico

GL _____
DF _____
KB _____

Spud Date: 9-28-81
Completion Date: 6-25-82

20" Conductor pipe set & cmt'd @ 40'

16" OD, 48 #/ft, grade _____
csg set @ 640 ' w/ 500 sxs.
Circ? Yes TOC @ _____ ' by _____. (Circ. 100 sxs)
(18 1/2" hole)

13 3/8", 48.0 + 54.50 #/ft csg set @ 1680' w 800 sxs
Circ. 100 sxs to sfc. (14 3/4" hole)

10 3/4" csg set @ 3864' w 500 sxs Circ. 125 sxs (12 1/4" hole)
(Drilled 12 1/4" hole to 5101', csg stuck @ 3864')

Current Perforations:

Bone Springs 8554'-60'
8568'-76' (Total 14 holes)

7 5/8" OD, _____ #/ft, grade _____, _____ thd
csg set @ 10,650 ' w/ 1900 total sxs in
2 stages w/ DV tool set @ 5534 '.
Stage 1 circ? _____ TOC @ _____ ' by _____.
Stage 2 circ? _____ TOC @ _____ ' by _____.
(9 1/2" hole)

LC+stuck @ 4393'. Fish,
Left Bit, reamer, 2 D.C., reamer
& shack sub in hole. Set cmt plug
& kicked off @ 2621'.

DV tool @ 5534'

CIB @ 8730' w
12' of cmt. on top

P670-8718'

Spot 100sx
plug

11,940 Spot 100sx plug

12,170 Spot 100sx plug

13,200 Spot 100sx plug

13,622

OH ID: _____"
COTD: _____"
PBD: 8719 "
TD: 13,622 "

Date: 11-19-93
Prepared By: BID

Proposed P+A
Well Equipment Schematic

Lease: Maddox Well: 1 Field: Antelope Ridge

Unit Letter L Location: 1980 feet F S L & 660 feet F W L, Section 12,
T-23-S, R-34-E Block _____, _____ Survey, Lea County, Texas New Mexico

GL _____
DF _____
KB _____

Spud Date: 9-28-81
Completion Date: 6-25-82

20" Conductor pipe set + cmt'd @ 40'

16" OD, 48 #/ft. grade
csg set @ 640 ' w/ 500 sxs.
Circ? Yes TOC @ _____ by _____. (Circ. 100 sxs)
(18 1/2" hole)

13 3/8", 48.0 + 54.50 #/ft csg set @ 1680' w 800 sxs
Circ. 100 sxs to sfc. (14 3/4" hole)

10 3/4" csg set @ 3864' w 500 sxs Circ. 125 sxs (12 1/4" hole)
(Drilled 12 1/4" hole to 5101', Csg stuck @ 3864')

Current Perforations:

Bone Springs 8554'-60'
8568'-76' (Total 14 holes)

7 5/8" OD, _____ #/ft. grade _____, _____ thd
csg set @ 10,650 ' w/ 1900 total sxs in
2 stages w/ DV tool set @ 5534' .
Stage 1 circ? _____ TOC @ _____ by _____.
Stage 2 circ? _____ TOC @ _____ by _____.
(9 1/2" hole)

Spot 100sx plug

11,940 Spot 100sx plug

12,170 Spot 100sx plug

13,200 Spot 100sx plug

13,622

LC + stuck @ 4393'. Fish,
Left Bit, reamer, 2 D.C., reamer
+ shock sub in hole. Set cnt plug
& kicked off @ 2621'.

DV tool @ 5534'
35' of cnt on top
CIB @ 8500'

CIB @ 8730' w
12' of cnt. on top

OH ID: _____
COTD: _____
PBD: 8718
TD: 13,622

Date: 11-19-93
Prepared By: BID