

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

1625 N. French Dr.
Hobbs, NM 88201

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-13838
2. Name of Operator J. C. Williamson	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P. O. Box 16, Midland, TX 79702	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit N, 660 FSL & 1980' FWL Sec. 10, T-23-S, R-34-E	8. Well Name and No. Lisa Federal #1
	9. API Well No. 30-025-27813
	10. Field and Pool, or Exploratory Area NW Antelope Ridge (Bone Springs)
	11. County or Parish, State Lea County, NM


12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-13-01 Set 3-1/2" CIBP @ 8856', dumbled 35' cmt. on CIBP.
12-13-01 Mix mud & circ. hole.
12-13-01 Spot 50 sx cmt. @ 8544' to 6940'.
12-13-01 Spot 25 sx cmt. @ 4928'.
12-14-01 Tag plug @ 4673'.
12-14-01 Spot 25 sx cmt. @ 2112'.
12-14-01 Cut 5-1/2" csg. @ 750'.
12-14-01 Spot 75 sx cmt. @ 800'.
12-15-01 Tag plug @ 521'.
12-15-01 Spot 25 sx cmt. from 50' to surface.
12-15-01 Install dry hole marker.



RECEIVED
2001 JAN 3 PM 1 07
BUREAU OF LAND MGMT.
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct

Signed Gary Gourley Title Agent Date 12-28-01
(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: