July 19, 1993

C.W. Stumoffer Ridge Lea Bank Building, Suite 1007 Fort Worth, TX 76116

SUBJECT: Subsequent Plugging Report Shipman Well #1-G, Sec.35, T-22S, R-37E

Gentlemen:

We have inspected the above-referenced well location and it is ready to be released. However, you have not filed a subsequent report of the actural plugging of this well, so we are unable to release the location.

We have written to you on previous occasions requesting this report and so far it has not been received.

Your prompt attention to this request is expected and further delay will be cause to turn this matter over to our attorney.

Very truly yours,

OIL CONSERVATION DIVISION

They want their bond veleased. Can HP

------

Communication and an an

Jerry Sexton District I, Supervisor

JS:dp

cc: Robert Stovall Oil Conservation Division Santa Fe, NM 87504-2088

n an Arran an Arra an A

1000