STATE OF NEW JERGY AND MINERALS

80. 01 COPICE RECEIVED	
DISTRIBUTION	
BANTA FE	
FILE	
U.S.O.S.	 ļ
LAND OFFICE	L
OPERATOR	

WELL X ame of Operator

ddress of Operator

ocation of Well UNIT LETTER ____ West

TY AND MINERALS DEPARTME	C _ CONSERVA	ATION DIVISION 0x 2088 V MEXICO 87501	Form C-103 Revised 10-1-78
ILE 18.0.8. AND OFFICE PERATOR			State Oil 6 Gas Lease No.
(DO NOT USE THIS FORM FOR PRO	Y NOTICES AND REPORTS ON PROBALS TO DRILL ON TO DELPEN OF PLUG 100 FOR PERMIT - " (FORM 6-101) FOR SU	BACK TO A DIFFERENT RESERVOIR.	7, Unit Agreement Name
of Operator	OTHER-		8. Farm or Lease Name
= *	leum Corporation		Hugh
ss of Operator	1		9. Well No.
P.O. Box 806	Eunice, New Mexi	co 88231	16
ion of Well			10. Field and Pool, or Wildcat
E 1	650 North	LINE ANDFEET	South Eunice - SA
WestLINE, SECTION	14 22S	37E	MEM.
	15. Elevation (Show whether 3361	DF, RT, GR, etc.)	12. County Lea
Check /	Appropriate Box To Indicate NITENTION TO:		Other Data IENT REPORT OF:
REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
ALTER CASING	CHANGE PLANS	OTHER	in Operating \omega
SEE RULE 1103.	erations (Clearly state all pertinent des	ails, and give pertinent dates, incli	ading estimated date of starting any proposed
Drilled 12½" h Twisted off bi RU Halliburton up hole to 300	ed 12½" hole @ 10:00 ole to 938' @ 12:15 t and bit sub, left and set 200' plug @ ' & circ. cement. ' East & spudded Hug	A.M. 2-1-84. in hole. 938'. WOC 6 hrs.	Tagged plug. Pulled 2-3-84.

15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:
PORABILY ABANDON OR ALTER CASING CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQS OTHER OTHER PROPOSED OF Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed spok) SEE RULE 1903.
1. MI RURT Spudded 12½" hole @ 10:00 P.M. 1-30-84. 2. Drilled 12½" hole to 938' @ 12:15 A.M. 2-1-84. 3. Twisted off bit and bit sub, left in hole. 4. RU Halliburton and set 200' plug @ 938'. WOC 6 hrs. Tagged plug. Pulled up hole to 300' & circ. cement. 5. Skidded rig 15' East & spudded Hugh 16Y @ 7:30 A.M. 2-3-84.
receby certify that the information above is true and complete to the best of my knowledge and belief. Field Foreman August 23, 1985
August 23, 1985 The state of Approval, IF ANY! Field Foreman OATE August 23, 1985 THE THE PROVAL, IF ANY!