

Submit 3 Copies  
to Appropriate  
District Office

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. N/A
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State "A" Account #1
8. Well No. 120
9. Pool name or Wildcat Langlie Mattix - SR - Qv - GB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> X OTHER Injection
2. Name of Operator Clayton W. Williams, Jr., Inc.
3. Address of Operator 6 Desta Drive, Suite 3000, Midland, Texas 79705
4. Well Location Unit Letter C : 25 Feet From The North Line and 1345 Feet From The West Line Section 10 Township 23S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3483 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Estimated Start Date: Upon Approval

- 1) MIRU.
- 2) POOH laying down cement lined tubing and packer.
- 3) Set CIBP @  $\pm$  3500', dump bail 10' of cement on CIBP.
- 4) Load hole w/ field salt water and test csg to 500 psi for 30 minutes.  
(Record test on pressure chart for subsequent report)
- 5) Temporarily abandon wellbore for future use.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

David Grafe

TITLE

Petroleum Engineer

DATE

12-8-92

TELEPHONE NO.

TYPE OR PRINT NAME

David Grafe

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

DATE

DEC 09 1992

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: