

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
V-732

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Exxon Corporation 3. Address of Operator P.O. Box 1600, Midland, TX 79702 4. Location of Well UNIT LETTER P 660 South LINE AND 660 FEET FROM THE East 18 TOWNSHIP 23S RANGE 33E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3697'-GR	7. Unit Agreement Name 8. Farm or Lease Name New Mexico 'DL' State 9. Well No. 6 10. Field and Pool, or Wildcat Cruz Delaware 12. County Lea
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. POH w/production equipment. Install BOP's.
2. POH w/tubing. If tbg anchor sticks while pulling out may need to make run with gauge ring.
3. RIHW/5-1/2" CIBP and set at 5050'. Dump bail 4 sx cement on top.
4. RIH w/tubing and test casing/BP to 500#. Circulate hole w/100 bbl. inhibited fresh water containing 20 gal. Corexit 7720 and 10 gals. Corexit 7672.
5. Leave killstring in hole. RIH w/rods. RDMO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rosemarie Whitlock TITLE Office Assistant DATE 5-22-86

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 2 1986