

6-1-85	306	BW	BH	400#
6-2-85	283	BW	BH	400#
6-3-85	312	BW	BH	400#
6-4-85	270	BW	BH	400#
6-5-85	321	BW	BH	400#
6-6-85	46	BW	BH	400#
6-7-85	263	BW	BH	375#
6-8-85	306	BW	BH	400#
6-9-85	287	BW	BH	400#
6-10-85	660	BW	BH	100#
6-11-85	660	BW	BH	100#
6-12-85	228	BW	BH	155#
6-13-85	300	BW	BH	200#
6-14-85	305	BW	BH	225#
6-15-85	315	BW	BH	325#
6-16-85	315	BW	BH	325#
6-17-85	279	BW	BH	325#
6-18-85	274	BW	BH	300#
6-19-85	272	BW	BH	325#

6-20-85 Prepare to CO Iron Sulfide & Scale
 RU Dresser Atlas ran junk basket & guage ring. Stopped
 @ 72' from surface. RD Dresser RUPU & RU TIH w/3 7/8" bit,
 Csg. Scraper, 2-3 1/8" DC. on 2 7/8" Tbg. tagged @ 70' Circ
 Out to 394' Tagged up hard @ this depth. RU Power swizel SOFN.

6-21-85 Resume CO
 CO Iron Sulfide & Scale to 2600' TOH. SDFN.

6-22-85 SD for Weekend.
 TIH w/Bit & Co to @ 3677' PBTD. Circ clean & TOH. RDPU &
 Hooked well head.

6-23-85 SD for Sunday.

6-24-85 Prepare to run Csg Inspection Log.
 SD for Sunday.

6-25-85 Resumed flowing back well
 RU Dresser & Ran Csg. Inspection Log. WO orders

6-26-85 Flowing Back wtr from 7 Rivers
 281 BW, BH 140#

6-27-85 Flowing Back wtr from 7 Rivers
 293 BW, BH 185#.

RECEIVED
DEC 2 - 1985
O.C.D.
HOBBS OFFICE

6-28-85 Flowing Back wtr from 7 rivers.
297 BW, BH 210#

6-29-85 Flowing Back Wtr
355 BW, BH 245#

6-30-85 Flowing Back Wtr
232 BW, BH 250#

7-1-85	289 BW	BH 300#
7-2-85	322 BW	BH 305#
7-3-85	276 BW	BH 340#
7-4-85	327 BW	BH 370#
7-5-85	298 BW	BH 370#
7-6-85	320 BW	BH 380#
7-7-85	339 BW	BH 390#
7-8-85	344 BW	BH 400#
7-9-85	422 BW	BH 345#
7-10-85	314 BW	BH 380#
7-11-85	321 BW	BH 395#
7-12-85	386 BW	BH 400#
7-13-85	284 BW	BH 410#
7-14-85	342 BW	BH 410#
7-15-85	504 BW	BH 390#
7-16-85	357 BW	BH 400#
7-17-85	364 BW	BH 410#
7-18-85	327 BW	BH 410#
7-19-85	257 BW	BH 410#
7-20-85	349 BW	BH 410#
7-21-85	369 BW	BH 350#
7-22-85	310 BW	BH 400#

7-23-85 Prepare to Fish.
MIRUPU RU Rotary Wireline Co. Ran Free point on 4½" csg & cut
csg @ 3315' & 3268'. RD Wireline Co. Pulled 78 Jts (3268')
plus 6' piece. SDFN.

7-24-85 Prepare to TOH w/ 7 7/8" Bit.
Installed 8" BOP. TIH w/ 7 7/8" bit, 4-4 3/4" D.C. on
2 7/8" D.P. Tagged up @ 3230'. CO to top of fish (47 piece 4½" Csg)
Pulled bit above 3000'. Hooked up flowline. SDFN.

7-25-85 Prepare to TOH w/shoe & wash pipe.
TIH w/ 7¼" Cutright shoe & 2 Jts. Wash pipe, D.C., on 2 7/8"
D.P. Tagged @ 3268'. Washed over to 3304' (@ DV Tool) Pulled up
hole to @ 3000'. SDFN.

7-26-85 Prepare to wah over fish.
Trip back to 3304' Washed over w/cutrite shoe on 2 Jts
wash pipe to 3313'. Shoe wore out. TOH w/shoe. SDFN.

RECEIVED
DEC 2 - 1985
OCCO
HOBBS OFFICE

7-27-85 Prepare to Fish Out Centerspear.
TIH w/4½" Center spear & tagged fish. TOH w/spear. Grapple was bent did not catch fish. TIH again w/Centerspear. Tagged Fish. Set Spear. TOH. Spear had unscrewed left in hole. SDFN.

7-28-85 SD for Sunday.

TIH w/screw in sub. Tagged up and tried to screw into Fish. TOH. Threads on screw in sub was tore up. Replaced Tbg. line. SDFN.

7-29-85 Prepare to TIH w/Washpipe & Center Spear.
SDF Sunday.

7-30-85 Prepare to Fish for Centerspear.
TIH w/4½" Center spear and DP Assembly. Tagged Fish didn't catch fish. TOH. (Centerspear had tore up.) TIH w/7½" overshot Assembly (Guide shoe w/4½" Dress off pads & cross over Bushing, & over shot bowl w/Grapple & 2' Extention, Top Sub, Jars, DC & DP. Tagged Fish @ 3315'. Washed over, Set Grapple & Pulled 120,000# on Fish before it came free. TOH w/47' piece of 4½" Csg. & DV Tool. SDFN.

7-31-85 Prepare to Dress off 4½" Csg stub.
TIH w/7½" Cutrite shoe w/wire & 2' extension, Jars, DC & 2 7/8" DP. Tagged on fill @ 3265' Picked up swivel & circ clean down to csg stub @ 3315' went over 4½" csg stub @ 2'. TOH w/Cutrite shoe. Did not retrieve center spear laid down wash pipe. SDFN.

8-1-85 Logging
TIH w/ 7 5/8" shoe & dress off mill tagged up on fill @ 3265'. Washed to 3308'. Milled from 3308' to 3311'. TOH w/shoe. (Shoe was wore out) but dress off Mill was like new. Didn't dress off 4½" Csg stub. (4½" Centerspear laying over stub. RU Wireline Co. Ran GR. w/Caliper Log. Couldn't get down. TIH w/2 7/8" DP to 3100'. Logged through DP from 3238' to 2400'. SDFN.

RECEIVED
DEC 2 - 1985
O.C.D. OFFICE
HOBBS OFFICE