



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

POST OFFICE BOX 1980
HOBBS, NEW MEXICO 88241-1980
(505) 393-6161

March 6, 2000

Texaco E&P Inc

ATT: Denise Leake
205 E Bender

Hobbs NM 88240

RE: REQUIRED GAS/OIL RATIO TEST

Gentlemen:

Your company has put A H Blinebry Federal NCT-1 #42-K, 33-22s-38e API #30-025-288 back on production and in doing so the Oil Conservation Division needs some more paper work to bring your well file up to date.

After a well has been put back on production a Gas/Oil Ratio Test is required to reassign your allowable to the well. You may put this test on the C-104 also stating your current transporters for the well. The C-104 has been revised February 10, 1994 because of the new ONGARD computer system. We have enclosed some copies of this form.

If you have any questions on this matter, please call the District I, Hobbs office (505) 393-6161.

Very truly yours,

OIL CONSERVATION DIVISION

Chris Williams; Supervisor, District I

JS:dp
cc:file

