

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240  
SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 38469
2. NAME OF OPERATOR Yates Petroleum Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 FSL & 1650 FEL, Sec. 30-T23S-R34E		8. FARM OR LEASE NAME Kestrel ABE Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3629' GR		10. FIELD AND POOL, OR WILDCAT Und. Bell Lake Bone Springs
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit 0, Sec. 30-T23S-R34E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input checked="" type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other) Set CIBP, Perforate, Treat	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4-30-85. Set CIBP at 9900' w/35' cement on top. WIH and perforated 8388-8457' w/15 .42" holes as follows: 8388, 89, 95, 96, 8415, 17, 21, 25, 29, 31, 42, 44, 48, 55 and 57'.

5-1-85. Acidized perfs 8388-8457' w/2000 gals 7½% Spearhead acid + 20 ball sealers.

5-3-85. WIH and perforated 8198-8295' w/16 .50" holes as follows: 8198, 8200, 05, 10, 19, 22, 26, 30, 33, 66, 68, 78, 82, 87, 92 and 95'.

5-4-85. Acidized perfs 8198-8295' w/3000 gals 7½% Spearhead acid and 25 ball sealers.

5-9-85. WIH and perforated 7573-7713' w/21 .42" holes as follows: 7573, 76, 86, 93, 97, 7607, 10, 13, 18, 25, 41, 44, 47, 54, 76, 7678, 81, 85, 7704, 05 and 13'. Acidized perfs 7573-7713' w/3000 gals 7½% NEFE acid + ball sealers.

5-15-85. WIH and perforated 7335-45' w/10 .50" holes as follows: 7335, 36, 37, 38, 39, 41, 42, 43, 44 and 45'. Acidized perfs 7335-45' w/1000 gals 7½% Spearhead acid and 8 ball sealers.

5-18-85. Frac'd well w/20000 gals gelled KCL water + 41000# 20/40 sand.

5-25-85. WIH and perforated 5254-5308' w/12 .50" holes as follows: 5254, 56, 58, 64, 66, 68, 5294, 98, 5300, 04, 06 and 08'.

18. I hereby certify that the foregoing is true and correct

SIGNED Quinta Goodlett TITLE Production Supervisor DATE 5-31-85  
(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JUN 4 1985

\*See Instructions on Reverse Side

RECEIVED  
JUN -5 1985  
G.C.D.  
HOBBS OFFICE