| OR Gerge side ()   | Expires August 5. LEASE DESIGNATION LC-030133 (b)  | 31, 1985<br>AND SERIAL NO  |
|--|--|--|
| )N'WELLS ack to a different reservoir. oposals.)                                     | 7. UNIT AGREEMENT NA   | /AB  |
|  | A PARM OR LEASE NA   | ve   |
| State requirements.*  RT, GR. etc.)  | 1 10. FIELD AND POOL, of Langley Straw 11. SHC., T., R., M., OR SURVEY OR ARM 28-22S-36E   | DE WILDCAT   |
| ( ) L  | 24 D-4-  |  |
|  |  |  |
| WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report result | ALTERING ABANDONM a of multiple completion pletion Report and Log f  | casing x   |
|  | Recommendation of Report, or Completion or Recommendation or Recom | (Other Instructions Proved State Designation   LC-030133 (b)   LC-030133 (b)   CC-030133 (b) |

Propose to P&A as follows:

| 1 5700-5800 26sx POH w/RBP. Set CIBP @ 5800. Circ hole w/10 ppg 35 vis MLF & Spot 100' cmt on CIBP. (Perfs 5827- 2 3650-3750 40sx Spot. (Queen) 3 3350-3500 40sx Spot. (Seven Rivers) |       |
|---|-------|
| 2 3650-3750 40sx Spot. (Oueen) しゅんさん  | 5947) |
| 2 3030 3730 103K Spot. (400tm)  |       |
| 3 3350-3500 40sx Spot. (Seven Rivers) 40 St   |       |
| 4 2900-3030 405X 3pot. (lates)  |       |
| 5 1200-1400 125sx Perf @ 1400. CR @ 1200. (Surface Shoe)  |       |
| 6 0- 50 32sx Perf @ 50'. Cmt in & outside 8-5/8" csg.   |       |

Install Dry hole marker

| Tech. Spec. DATE 12-15-86 |
|---------------------------|
| 1257                      |
| DATE 1-135                |
|                           |

## \*See Instructions on Reverse Side