

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well. Use "APPLICATION FOR PERMIT" for such proposals.)

HOBBS, NM 88240

LEASE DESIGNATION AND SERIAL

LC-030133(b)

IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

FARM OR LEASE NAME

Langley Meyers

WELL NO.

1

FIELD AND POOL OR WILDCAT

Langley Strawn

SEC. T., E., M., OR BLE. AND SURVEY OR AREA

Sec 28-22S-36E

COUNTY OR PARISH STATE

Lea

N.M.

WELL ☒ GAS WELL ☐ OTHER

NAME OPERATOR ARCO Oil and Gas Company
Division of Atlantic Richfield Company

ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1880' FNL & 1650' FEL (Unit letter G)

PERMIT NO.

ELEVATIONS (Show whether FE, FL, OR, etc.)

API #30-025-29295

3498.4' GL

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SPILLAGE REPORT OF:

LONG WATER SHUT-OFFS

STOP OR ABANDON CASING

WATER SHUT-OFF

REPAIRING WELL

CHANGING TREAT

COMPLETE COMPLETION

FRACURE TREATMENT

ALTERING CASING

STOP OR ABANDON

ABANDON*

SHUTTING OR ABANDONING

ABANDONMENT*

CEASE WELL

CEASE PLANT

(Other)

Other Test Glorieta & Paddock Zones X

(NOTE: Report results of multiple completion on Well Completion or Re-completion Report and Log form.)

1. If a well is proposed to be drilled, completed, or re-completed, clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is to be abandoned, give subsurface locations and measured and true vertical depths for all markers and zone perils (pertinent to this well).

Propose to test the producing capabilities of the Glorieta and Paddock zones in the following manner:

1. MIRU. NU BOP.
2. RIH w/bit, CO to 6110'. Set CIBP @6100'.
3. Perf Paddock w/1 JSPF @ 5982, 85, 86, 91, 92, 97, 99, 6004, 05, 09, 11, 13, 23, 24, 31, 32, 35, 36, 41 (19 holes).
4. RIH w/FBRC, set @ 5880'. Pressure test annulus to 500#. Acidize Paddock 5982-6041' w/3000 gals 15% NEFE. Swab test.
5. POH w/pkr. Set RBP @ 5960'. Pressure test csg to 1000#. Perf Glorieta w/1 JSPF @ 5827, 29, 31, 32, 34, 45, 46, 50, 55, 61, 63, 73, 75, 81, 97, 99, 5901, 03, 06, 07, 34, 36, 37, 40, 44, 46, 5947' (27 holes).
6. Set pkr @ 5730', press test annulus to 500#. Acidize Glorieta 5827-5947' w/5000 gals 15% NEFE. Swab test.
7. POH w/pkr. RIH w/compl assy.

1. I hereby certify that the foregoing is true and correct.

SIGNED *W.D. McDaniel*

TITLE Dist. Dir. Supv

DATE 10/11/85

(Use space for Federal or State office use)

APPROVED BY *Don Wood*

TITLE *Adm. Asst.*

DATE 10/17/85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

OCT 21 1985

OFFICE
HONORARY