

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Delaware	4090'	5057'	Sand, fine grain, gray and wet.

38. GEOLOGIC MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Anhydrite	1165'	1165'
Salado Salt	1310'	1310'
Base Lower Salt	4700'	4700'
Delaware Lime	4942'	4942'
Delaware Sand	4090'	4090'