

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM Oil Co
P 1000
HCD NM 30

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 397-0431

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter E : 1980 Feet From The NORTH Line and 450 Feet From The
WEST Line Section 33 Township 22S Range 38E

5. Lease Designation and Serial No.
LC 032104

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
BLINEBRY, A. H. FEDERAL NCT-1
43

9. API Well No.
30 025 29353

10. Field and Pool, Exploratory Area

DRINKARD S Branson Dr. Abo

11. County or Parish, State
LEA, NEW MEXICO

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ OTHER: _____
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work,)*.

- 1) MIRU PU. TOH W/ RODS AND PUMP. NU BOP. TOH W/TUBING.
- 2) TIH W/ CMT RETAINER AND SET AT 5460'.
- 3) MIRU DS. SQUEEZE PADDOCK PERFS (5518'-5556') W/50 SX CLASS C CEMENT W/ FLUID DISPERSANT AND TAIL IN W/ 50 SX CLASS C NEAT CEMENT. SHUT DOWN, LET CEMENT SET.
- 4) TOH W/ TBG. TIH W/ BIT & CSG SCRAPER. DRILL OUT CMT RETAINER & CMT TO PBTD @ 6311'. TEST SQUEEZE BY CLOSING BOP & PRESS. UP ON WELL TO 500# AT SURFACE. DRILL OUT CIBP & CMT CAP @ 6311'. DRILL TO PBTD @ 7459'. TOH W/ BIT.
- 5) TIH W/ PKR & SET AT 6350'. LOAD BACKSIDE BUT DO NOT PRESS UP. KEEP BKSIDE LOADED THROUGHOUT THE ACID JOB.
- 6) MIRU DS. ACIDIZE DRINKARD PERFS W/ 4500 GLS 15% NEFE HCL IN 3 1500 GAL STAGES W/ 1K# SALT BLOCKS BETWEEN EACH STAGE. MAX PRESS FOR ACID JOB IS 5K#. SD, RD DS.
- 7) TOH W/ TBG AND PKR.
- 8) TIH WITH TUBING. TIH W/ RODS AND PUMP. RETURN WELL TO PRODUCTION.

14. I hereby certify that the foregoing is true and correct.

SIGNATURE V. Greg Maes TITLE Engineering Assistant

TYPE OR PRINT NAME V. Greg Maes

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ALEXIS C. SWOBODA TITLE PETROLEUM ENGINEER

DATE

CONDITIONS OF APPROVAL, IF ANY:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED
1997 JUL 31 A 9:39
BUREAU OF LAND MGMT.
ROSWELL OFFICE