Γ.					NEW MEXICO OIL CONSERVALION COMMISSION FIELD TRIP REPORT			
I N S	C L A	FAC	H O U	Q U A		TEED THIT REFORM		
P E	l s	I L	RS	R T	Name Durward R. Smith	Date 1/9/92	Miles 187 District I	
CT	F	T		E R	Time of Departure <u>7 AM</u>			
F S I R R E S I S T C F I E E T I T R Time of Departure 7 AM Time of Return 6 PM I C Y H In the space below indicate the purpose of the trip and the dutie N T O A H D D						d the duties		
	I O N		U performed, listing wells or leases visited and any action taken.					
		 		s	Signature			
0	0	Ο	4		Work in office.			
Р	٤	D	6		1 Well - Went to location of Michael Morris - Baker C #2 to respot cement plug across 8 5/8 casing shoe. Cement company nor company man were on location. Waited on Dowell to arrive on location. I went back to the office at 3:00 PM and received a call at 3:50 PM that they were mixing cement. I drove back to the location at 7:00 PM to witness tagging of plug. Plug was soft, but hole was standing full of fluid and top of cement showed to be around 1087'. I called it good and returned home at 9:00 PM.			
					<u>Mileage</u> UIC <u>187</u> RFA Other	<u>Per Diem</u> UIC RFA Other		
						Other	Other <u>4</u>	
TYPE INSPECTION INSPECTION PERFORMED CLASSIFICATION						NATURE OF SPECIFIC WELL		
PC T R F W	= Pli = Pli = Wel = Rep = Wat = Mis	useke uggin uggin ll Te bair/l terfl terfl ter Co	9 g Cle st Worko DV Dr Sp	anup ver	<pre>U = Underground Injection C related to injection pri- resulting from injection injection and production tests, surface injection R = Inspections relating to D = Other - Inspections not Reclamation Fund E = Indicates some form of a</pre>	ontrol - Any inspection of or oject, facility, or well or n into any well. (SWD, 2ndry n wells, water flows or pressur n equipment, plugging, etc.) Reclamation Fund Activity related to injection or The enforcement action taken in the below the letter U, R or O)	operations S = SWD U = Underground Storage G = General Operation F = Facility or location	