Submit 3 Copies to Appropriate

## State of New Mexico ٦t

Form C-103 Revisied 1-1-89

District Office

P.O. Box 2088

Energy, Minerals and Natural Re	sources Departmen
<b>OIL CONSERVATION</b>	DIVISION

On the Follow Mordon (	7704 0000
DISTRICT   Santa Fe, New Mexico 8	3/504-2088
P.O. Box 1980, Hobbs, NM 88240	
<u>DISTRICT II</u>	API NO. (assigned by OCD on New Wells)
P.O. Drawer Dd, Artesia, NM 88210	30-025-31610
DISTRICT III	E. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, Nm 87410	STATE FEE X
	5. State Oil & Gas Lease No.
	N/A
SUNDRY NOTICES AND REPORTS ON WE	ELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	RMIT" ARROWHEAD GRAYBURG UNIT
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	
OIL GAS	
WELL X WELL OTHER	
2. Name of Operator	81. Well No.
CHEVRON U.S.A. INC.	234
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	ARROWHEAD/GB
4. Well Location	750
O'AT ESSECTION OF THE PROPERTY	OUTH Line and 750 Feet From The WEST Line
Section 18 Township 22S	Range 37E NMPM LEA County
10. Elevation(Show whether	
34	-34 GE
11 Check Appropriate Box to Indecate Nature of Noti	ce, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	ILLING OPNS. PLUG AND ABAN.
PULL OR ALTER CASING CASING TEST A	ND CMT JOB
<u> </u>	MPLETION SUMMARY X
12. Describe Proposed or Completed OperationalClearly state all pertinent details, and give pert	inent dates, including

Describe Proposed or Completed Operations(Clearly state all per esticated date of starting any proposed work) SEE RULE 1103.

MIRU DRILL OUT CEMENT AND FLOAT TO 3858. PERFORATE 3850-3608, WITH 4" GUNS AND 180 DEG. PHSD. ACIDIZE PERFS WITH 8 BBLS OF 15% NEFE. SWAB BACK ACID. PERFORATE WITH 4" GUNS, 2 JHPF 180 DEG. PHSD, 3762-3608. ACIDIZE PERFS WITH 15% NEFE, SWAB BACK ACID. TIH WITH TBG. AND RODS. WELL COMPLETED ON 8-6-92.

	mation above is true and comp	TITLE	TECH. ASSISTANT	DATE:	8-27-92
TYPE OR PRINT NAME P.R. MATTHEWS			TELEPHONE NO. (915)687-7812		
ORIGINAL SIGNED BY JERRY SEXTON  APPROVED BY  PISTURE OF APPROVAL PLANT I SUPERVISOR			DATE	AUG 31'92	

RECEIVED
AUG 2 8 1992
CCD HOBBS OFFICE

Submit 3 Copies to Appropriate State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103

District Office OIL CONSERVATION DIVISION P.O. Box 2088	Hevisied 7-1-89				
DISTRICT I Santa Fe, New Mexico 87504-2088 P.O. Box 1980, Hobbe, NM 88240					
DISTRICT II P.O. Drawer Dd, Artesia, NM 88210	API NO. (seeigned by OCD on New Wells) 30-025-31610				
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410	Indicate Type of Lease     STATE FEEX				
	6. State Oil & Gas Lease No.				
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:	7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT				
OIL GAS WELL OTHER					
2. Name of Operator CHEVRON U.S.A. INC.	8. Well No. 234				
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	9. Pool name or Wildcat ARROWHEAD/GB				
Unit Letter L : 1880 Feet From The SOUTH Line and Section 18 Township 22S Range	750         Feet From The LEA         WEST Line County				
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  SUBSEQUENT RE REMEDIAL WORK  COMMENCE DRILLING OPNS.  CASING TEST AND CMT JOB  OTHER:  OTHER:  DRILLING SUMMA	ALTER CASING PLUG AND ABAN.				
Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent detes, including esticated date of starting any proposed work) SEE RULE 1103.					
MIRU ROD-RIS DRILLING ON 7-3-92 AND SPUD 12 1/4" HOLE.  DRILL FROM 0' - 1151'. RUN 8 5/8" CASING FROM SURFACE TO 1151'.					
PUMP 750 SXS. CEMENT AND CIRCULATE 300 SXS. TO SURFACE.					
WAIT ON CEMENT FOR 14 HOURS AND DRILL OUT CEMENT AND FLOAT.					
TEST CASING TO 1000 PSI-OK.					
DRILL AND SURVEY FROM 1151'-3857'.					
RUN 5 1/2" CASING AND PUMP 850 SXS. CEMENT, CIRCULATE 170 SXS INSTALL WELLHEAD AND TEST, RELEASE RIG ON 7-9-92.	i. TO SURFACE.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNITURE	DATE: 7-14-92				
TYPE OR PRINT NAME P.R. MATTHEWS	TELEPHONE NO. (915)687-7812				
ORIGINAL SIGNED BY JERRY SEXTON  APPROVED BY DISTRICT I SUPERVISOR TITLE	JUL 17'92				
CONDITIONS OF APPROVAL, IF ANY:					