Form 3160-5 (November 1994)	UNITED STATES DEPAINTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED Budget Bureau No. 1004-0135 Expires July 31, 1996		
SUNDRY NOTICES AND REPORTS ON WELLS * 1980					5. Lease Serial No. NM 86927	
Do not use this form for proposals to drill or to re-enter and 8824 abandoned well. Use Form 3160-3 (APD) for such proposals.					lottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other Instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well X Oil Well	Gas Well	Other		8. Well Name an	d No.	
2. Name of Operator BURLINGTON RESOURCES OIL AND GAS COMPANY					Little Jack 30 Federal No. 1	
3a. Address	3b. Phone No. (include area code) 30-025-32176					
P. O. Box 51810, Midland, TX 79710-1810 915/688-9012 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					10. Field and Pool, or Exploratory Area West Triste Draw Delaware South Sand Dunes Bone Spring	
1980' FSL & 2310' FEL, Sec. 30, T23S, R32E					11. County or Parish, State Lea, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	Deepen	Production	n (Start/Resume)	Water Shut-Off	
X Notice of Intent	Alter Casing	Fracture Treat	Reclamatio	n	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplet	x Other Add Delaware Perfs		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporari	rily Abandon		
	Convert to Injection	Plug Back	Water Dis	posal		
13. Described Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the						

proposal is to deepen directionally or recomplete' horizontally give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Burlington Resources Oil and Gas Company intends to add additional Delaware perfs as follows:

MIRU. Unseat rods and pump. Release TAC. TOH w/ BHA and tubing. PU bit, csg scraper, and tbg. TOH w/ bit and scraper. Set CIBP at ~8600'. Perf Delaware w/ 4" casing gun loaded w/ 2 spf from 8282' to 8286' (10 holes) and from 8320' to 8337' (36 holes). Swab. If necessary, acidize with 1500 gallons 15% Ferchek SC acid and 70 balls. Swab. If necessary, frac down 2 7/8" tubing with 29,000 gals Delta Frac 25 and 75,200 lbs 20/40 Ottawa sand. Drill out sand fill and CIBP at 8600'. Push CIBP below 8800'. Reverse circulate hole clean. Set Baker Retrievamatic packer and tubing at 8200'. Swab until samples clean up.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Deborah Magness	Title	Regulatory Assistant				
Signature Delagach Magness		March 17, 1998				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by (ORIG. SGD.) ALEXIS C. SWOBODA	Tille FETR	OLFUM ENGINEEPate MAR 1343				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	I				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully or fraudulent statement or representations as to any matter within its jurisdiction.	to make to an	y department or agency of the United States any false, fictitious				

(Instructions on reverse)