Form 3160-5 (November 1994)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED Budget Bureau No. 1004-0135 Expires July 31, 1996		
SUNDRY NOTICES AND REPORTS ON WELLS				 Lease Serial No. NM 86927 If Indian, Allottee or Tribe Name 		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					once or Tribe Name	
SUBMIT IN TRIPLICATE - Other Instructions on reverse side				7. If Unit or CA	/Agreement, Name and/or No.	
1. Type of Well	Gas Well	Gas Well Other		8. Well Name and No.		
2. Name of Operator	Name of Operator			Little Jack 30 Federal No. 3		
BURLINGTON RESOURCES OIL AND GAS COMPANY 3a. Address 3b. Phone No. (include area code)				9. API Well No. 30-025-32478		
P. O. Box 51810, Midland, TX 79710-1810 915/688-9012 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 915/688-9012					10. Field and Pool, or Exploratory Area Triste Draw Delaware South Sand Dunes Bone Spring	
660' FSL & 2310' FEL, Sec. 30, T23S, R32E				11. County or Parish, State Lea, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	Deepen	Production	n (Start/Resume)	Water Shut-Off	
X Notice of Intent	Alter Casing	Fracture Treat	Reclamati	on	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomple	Market Mother Add Tresnor Sand Pay		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporar	Temporarily Abandon		
	Convert to Injection	Plug Back	Water Dis	posal		
13. Described Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the						

proposal is to deepen directionally or recomplete' horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion, in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Burlington Resources Oil and Gas Company intends to add Tresnor Sand pay as follows:

GIH w/ 4 $\frac{3}{4}$ " bit and casing scraper on 2 7/8" tubing to PBTD @ 8854'. Pull tubing, scraper, and bit. Perf 8610'-8613', 8616'-8618', 8625'-8627', 8630'-8632', and 8649'-8657' (44 holes). Acidize down 2 7/8" tubing with 1500 gals 15% Ferchek SC. If frac is warranted, reset packer at 8500'. Frac down 2 7/8" tubing with 30,000 gals Delta Frac 200 and 100,000 lbs 20/40 Super DC sand. SION. Bleed off pressure. Clean out sand fill to PBTD @ 8854'. Reverse circulate hole clean. Set 2 7/8" tubing at ~8500'. Return to production.

14. I hereby certify that the foregoing is true and correct.						
Name (Printed/Typed) Deborah Magness	Title	Regulatory Assistant				
Signature Deliarato Magaza	Date	March 12, 1998				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Title	Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office					
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.						
(Instructions on reverse)						

