

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and all recoveries):

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME		
				MEAS. DEPTH	TOP	TRUE VERT. DEPTH
0'	1065'		REDBEDS	RUSTLER	1065'	
1065'	1390'		ANHYDRITE	SALADO	1390'	
1390'	4425'		SALT, ANHYDRITE	CASTILLE	4425'	
4425'	4670'		ANHYDRITE	DELAWARE	4670'	
4670'	8560'		SAND, LIMESTONE, SHALE	BONE SPRING	8560'	
8560'	TD		LIMESTONE, SHALE			