

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. 15 SMITH ROAD, MIDLAND, TX 79705 915-687-737

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter B : 810 Feet From The NORTH Line and 1980 Feet From The

EAST Line Section 31 Township 23-S Range 32-E

5. Lease Designation and Serial No.

NM 18848

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
SDE '31' FEDERAL

5

9. API Well No.
30-025-32717

10. Field and Pool, Exploratory Area
TRISTE DRAW, DELAWARE, WEST

11. County or Parish, State
LEA, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

TYPE OF ACTION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Attering Casing
☒ OTHER: RECOMPLETE

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CHEVRONTXACO INTENDS TO RECOMPLETE THE SUBJECT WELL TO THE BRUSHY CANYON POOL.

- 1) MIRU PU. NUWH. INSTL BOP.
- 2) TIH W/BIT & BAILER. C/O TO BELOW 9044.
- 3) TIH W/PROD TBG & PKR. SET PKR @ 8900. RDP. SET PRESSURE BOMB IN F-NIPPLE. IF ZONE IS DEPLETED TA BOTH BONE SPRINGS BY SETTING CIBP @ 8970 & CAP W/35' CMT. SET CIBP @ 8600. CAP W/35' CMT.
- 4) INSTL TREE SAVER. ACID TREAT & FRAC STIMULATE LOWER BONE SPRINGS.
- 5) SWAB/FLOW BACK.
- 6) TIH W/PERF GUNS & PERF 7220-30, 7272-68, 7278-86'.
- 7) PUMP 1500 GALS 7 1/2% NEFE HCL.
- 8) FRAC STIM BRUSHY CANYON W/40,000# 100% RESIN COATED SAND.
- 9) TIH W/BIT & BAILER. C/O TO PBTD @ 8565'.
- 10) TIH W/PROD TBG. SET SN @ 50' BELOW LOWERMOST PERF. REM BOP.
- 11) INSTL RDS. REM STRIPPER HEAD & INSTALL POLISH RD.
- 12) PLACE WELL ON PRODUCITON & TEST.

14. I hereby certify that the foregoing is true and correct

SIGNATURE *J. Denise Leake* TITLE Regulatory Specialist DATE 6/13/2002

TYPE OR PRINT NAME J. Denise Leake

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: TITLE DATE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.