Form 3160-5 (JUNE 1990)

X

Notice of Intent

Subsequent Report

Final Abandonment Notice

DEPARTMENT OF THE INTERIOPO. Box 1980 BUREAU OF LAND MANAGEMEN NM 88241

FORM APPROVED
Budget Bureau No. 1004-013

Duaget Di	пеац	NO.	1004 -	013
Expires	s: Ma	rch 3	1, 1993	

						-, -		
5.	Lease	Designati	ion	and	Se	rial	N	

NM-84728

SUNDRY NOTICES AND REPORTS ON WELL	_LS
------------------------------------	-----

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

6. If Indian, Allottee or Tribe Name

Change of Plans

New Construction

Water Shut-Off

Dispose Water

Non-Routine Fracturing

Conversion to Injection

Report results of multiple completion on Well

SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation		
1. Type of Well Oil Gas Well Well X Ot	Plugged and Abandoned STRATA PRODUCTION COMPA	NY	8. Well Name and No. Codorniz Federal #2 9. API Well No.	
3. Address and Telephone No.	P. O. Box 1030 Roswell, New Mexico 88202-10	030 505-622-1127	30-025-32972 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description)		Diamondtail Delaware	
	1850' FNL & 330' FEL Section 15-23S-32E		11. County or Parish, State Lea County, New Mexico	
12. CHECK APPRO	PRIATE BOX(s) TO INDICATE NAT	URE OF NOTICE, REPO	RT, OR OTHER DATA	
TYPE OF SUBMISS	ION	TYPE OF ACTION		

			Completion or Recompletion Report and Log form.)
3.	Describe Proposed or Completed Operations (Clearly state a give subsurface locations and measured and true vertical depths f	I pertinent details, and give pertinent dates, including estimated da or all markers and zones pertinent to this work.)*	ate of starting any proposed work. If well is directionally drilled,

Abandonment

Recompletion

Plugging Back

Casing Repair

OTHER

Altering Casing

In accordance with discussions with Shannon Shaw, Carlsbad BLM, Strata Production Company requests approval to finalize the plugging of the well in the following manner:

- 1. Ml. Dig out cellar and Dry Hole Marker. Clean out.
- 2. RU. PU and TIH with one-inch to +/- 600'. Set cement plug as per Federal Regulations.
- 3. Pull one-inch. Weld plate. Set Dry Hole Marker. Fill cellar and clean location.

(This space for Federal College of College o	Title PETROLEUM ENGINEER	Date	AUG 28 1	333
14. I hereby certify that the foregoing is true and correct Signed Aral f. Sarces	Title Production Records Manager	Date	8/16/96	
682-582' W/505X, 60-0' W/205X.				30.7 (10.7 (1.1)
7142-7042' W/505X,			F-:	(
5126-5026 W/SOSX,				· • •
Plugs set on 06-19-95 as to 2836-8736', W/505X	follows:		20 (2) (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	
4. Completion of operation	ons by November 30, 1996.			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



