

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33574
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-4297
7. Lease Name or Unit Agreement Name	Coriander AOC State
8. Well No.	2
9. Pool name or Wildcat	Red Tank Bone Springs
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3731' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	OCT 31 1996
2. Name of Operator YATES PETROLEUM CORPORATION	OIL CON. DIV.
3. Address of Operator 105 South 4th St., Artesia, NM 88210	DIST. 2
4. Well Location Unit Letter H : 1650 Feet From The North Line and 330 Feet From The East Line Section 1 Township 23S Range 32E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3731' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & frac <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-19-21-96 - Cleaned location and set anchors. Moved in and rigged up pulling unit.
10-22-96 - Rigged up wireline. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging tools. TIH with 4" casing guns and perforated 9007-9045' w/28 .42" holes as follows: 9007-9017' and 9029-9045'. TOOH with casing guns and rigged down wireline. Nippled up frac head. Frac'd perforations 9007-9045' with 86000 gallons 30# crosslink gel, 226000# 20-40 Ottawa sand and 36000# 20-40 Super DC sand. Shut well in overnight.
10-23-96 - Opened well up and bled down to pit. Removed frac head and installed BOP. TIH with seating nipple and 2-7/8" tubing. Tagged sand at 8974'. Reversed 144' of sand out of hole to 9118'. Laid down 6 joints of 2-7/8" tubing. Removed BOP and nipped up wellhead. Swabbing.
10-24-96 - Swabbing.
10-25-96 - Swabbing.
10-26-96 - Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Oct. 30, 1996
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) RECEIVED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 14 1996

CONDITIONS OF APPROVAL, IF ANY: