

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-33826

Indicate Type of Lease

STATE ☐

FEE ☒

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS

WELL ☐

OTHER

Name of Operator
TITAN RESOURCES I, INC.

Lease Name or Unit Agreement Name
BRUNSON ARGO

Address of Operator
500 W. TEXAS, SUITE 500, MIDLAND, TEXAS 79701

Well No.
23

Pool name or Wildcat
WANTZ ABO

Well Location

Unit Letter E : 1800 Feet From The NORTH Line and 560 Feet From The WEST Line

Section 10 Township 22S Range 37E NMPM LEA County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3407' GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-15-97 MIRU PULLING UNIT; NU BOP ; RIH W/ 6 1/4" BIT; TAGGED CMT @ 3845'.
7-16-97 DRILLED OUT CMT AND DV TOOL TO 4003'; TESTED CSG TO 1000 PSI; CLEANED OUT 7" CASING TO 7284' - PBTD; POOH.
7-17-97 RAN Cased HOLE LOGS
7-19-97 RIH W/ 2 7/8" TBG TO 7219'.
7-22-97 SPOTTED 500 GAL 15% NEFE HCL AT 7219'; POOH W/ TBG; PERFORATED ABO W/ 2, 0.78" HOLES AT 7195'; RIH W/ 2 7/8" TBG TO 7152'.
7-23-97 ACIDIZE PERFS @ 7195' W/ 500 GAL 15% NEFE HCL; FRAC W/ 23,000 GAL & 12,000 LB SAND; START SWABBING BACK LOAD WATER.
7-24-97 SWABBED & FLOWED BACK LOAD WATER.
7-25-97 SWABBED & FLOWED BACK LOAD WATER & GAS.
7-26-97 SWABBED & FLOWED BACK LOAD WATER.
7-27-97 POOH W. TBG RIH W/ RBP & SET @ 7150'; PERFORATED ABO W/ 2, 0.78" HOLES @ 6994'; RIH W/ TBG TO 7004'.
7-28-97 CIRC. HOLE CLEAN.
7-29-97 ACIDIZE PERFS @ 6994' W/ 500 GAL 15% NEFE HCL; FRACED W/ 4000 GAL & 2000 LB SAND; STARTED FLOWING BACK WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRODUCTION OPERATIONS MANAGER DATE 08-27-97

TYPE OR PRINT NAME BRUCE WOODARD

TELEPHONE NO. 915-498-8661

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 07 1997

7-30-97 THRU 8-3-97 SWABBED & FLOWED BACK LOAD WATER.

8-5-97 POOH W/ TBG; SET RBP ON WIRELINE @ 6950'; PERFORATED ABO @ 6798' W/ 3, 0.78" HOLES.

8-6-97 RIH W/ TBG & PKR TO 6699'.

8-7-97 SPOTTED ACID @ 6793'; ATTEMPTED TO BREAK DOWN PERFS.

8-8-97 RE-PERORATED ABO FROM 6797' TO 6799' W/ 18 SHOTS; SPOTTED 500 GAL 15% NEFE HCL @ 6826'; ACIDIZED W/ 500 GAL 15% NEFE HCL & FRACED W/ 23,000 GAL & 12,000# SAND; STARTED FLOWING BACK LOAD WATER.

8-9-97 THRU 8-12-97 SWABBED & FLOWED BACK WATER.

8-13-97 POOH W/ TBG; RIH W/ BAILER & CLEANED OUT TO 6950'; RETRIVED RBP @ 6950'; CLEANED OUT TO 7150'.

8-14-97 RETRIEVED RBP @ 7150'; CLEANED OUT TO 7284'; RIH W/ 2 3/8" PRODUCTION TBG.

8-15-97 FINISHED RUNNING 2 3/8" TBG; SET @ 7239'; SWABBED AND FLOWED WELL.

8-16-97 RIH W/ PUMP & RODS & STARTED PUMPING WELL.