

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Code
P.O. F. 1997
Hobbs, NM

FORM APPROVED
Budget Bureau No. 1001-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals.

5. Lease Designation and Serial No.
NM 063228

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Burlington Resources Oil & Gas Company

3. Address and Telephone No.

P.O. Box 51810 Midland, Texas 79710-1810 915-688-6943

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2410' FSL & 1650' FEL
Sec. 24, T23S, R32E

8. Well Name and No.

Red Deer '24 # 1
Federal

9. API Well No.

30-025-3955

10. Field and Pool, or exploratory Area

Diamondtail Bone Spring
Wildcat Delaware

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Dry Hole-Plugging

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

BR respectfully requests to plug and abandon this location. Received verbal notification of plugging procedure from Joe Lara in Carlsbad office this date, 5/27/97.

Set. bottom plug @ 7000' with 150' plug
set plug @ top of Delaware (5048'), 50' above and below-estimated 50 sxs
Set plug @ csg shoe of 7" (4830'), 50' above and below-estimated 100 sxs, WOC and tag
Set plug @ surf csg shoe (679') with 100' plug and then do surf plug OR set plug @ 679' and bring up to surface.

14. I hereby certify that the foregoing is true and correct

Signed

Title Regulatory Compliance

Date 5/27/97

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: