Office	State	of New Me	XICO		Form C	
District I	Energy, Minera	ls and Natu	ral Resources	WELL API NO.	Revised March 25,	1999
1625 N. French Dr., Hobbs, NM 88240 District II				30025-34924		
811 South First, Artesia, NM 88210	OIL CONSE			5. Indicate Type	o∳ Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco			STATE	FEE 🗆	
District IV	Santa	Fe, NM 87	505		as Lease No.	
2040 South Pacheco, Santa Fe, NM 87505				o. State on a	sub Deuse 110.	
(DO NOT USE THIS FORM FOR PROPOSITION OF THE PROPOSALS.)  1. Type of Well	CATION FOR PERMIT" (FO	EEPEN OR PLU	JG BACK TO A R SUCH	7. Lease Name of TOMCAT '16' S	r Unit Agreement Na STATE	me:
Oil Well Gas Well	Other			7 37 1137	·····	
2. Name of Operator				7. Well No.	8	
CONCHO RESOURCES INC.  3. Address of Operator				8. Pool name or		
<ol> <li>Address of Operator</li> <li>W. LOUISIANA STE 410; MI</li> </ol>	IDLAND TX 79701			WILDCAT; BC		
4 Well Location						
ı	t let					
Unit Letter N:	600 feet from the	SOUTH lin	e and1830	_feet from the	WESTline	
0-4	T	120 D-	nga 22E	NIM DIM I I	A County	
Section 16	Township  10. Elevation (Show		nge 32E	NMPM LE	A County	
	3692' GR	v waeinei DI	i, Mad, RI, UK, Ell			
11. Check A	Appropriate Box to	Indicate Na	ture of Notice.	Report or Other	Data	
NOTICE OF IN				SEQUENT RE		
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WO					ALTERING CASIN	ig 🗆
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DI			ILLING OPNS. 🗌	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			
OTHER:			OTHER: SPUD \	WELL & SET CSG		Ä
		11				
12. Describe proposed or complet of starting any proposed work) or recompilation.	). SEE RULE 1103. F	y state all per or Multiple (	completions: Attac	give pertinent dates, h wellbore diagram	including estimated of proposed comple	date tion
of starting any proposed work)	). SEE RULE 1103. F M MDT. SET @ 660'. CMT W	or Multiple C	Completions: Attac	h wellbore diagram	of proposed comple	date tion
of starting any proposed work) or recompilation.  04/22/00 SPUD WELL @ 3:30 Pl 04/24/00 RIH W/ 13-3/8" CSG & ADDITIVES. CIRC 209	). SEE RULE 1103. F M MDT. SET @ 660'. CMT W O SX TO PIT. WOC.	or Multiple C	Completions: Attac	th wellbore diagram  C+ ADDITIVES; Table 1. Analyst DAT	of proposed comple	date tion
of starting any proposed work) or recompilation.  04/22/00 SPUD WELL @ 3:30 Pl 04/24/00 RIH W/ 13-3/8" CSG & ADDITIVES. CIRC 209  I hereby certify that the information SIGNATURE  Type or print name Terri S (This space for State use)	M MDT. SET @ 660'. CMT WOOS.  SET word word.	or Multiple Con Mu	ompletions: Attace  O SX 35/65 POZ Control  Production	th wellbore diagram  C+ ADDITIVES; Table 1. Analyst DAT	of proposed comple  AIL: 250 SX C +  TE_4-25-00  . 915-683-7443	date
of starting any proposed work) or recompilation.  04/22/00 SPUD WELL @ 3:30 Pl 04/24/00 RIH W/ 13-3/8" CSG & ADDITIVES. CIRC 209  I hereby certify that the information SIGNATURE Type of print name Terri S	M MDT. SET @ 660'. CMT WOOSX TO PIT. WOC.	or Multiple Con Mu	Completions: Attac	th wellbore diagram  C+ ADDITIVES; Table 1. Analyst DAT	of proposed comple  AIL: 250 SX C +	date