

Submit 3 Copies to Appropriate District

Office

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

1220 South St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Drive
Santa Fe, NM 87505

FORM C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35269
1. Type of Well: <input checked="" type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
2. Name of Operator Apache Corporation		6. State Oil & Gas Lease No.
3. Address of Operator 2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400		7. Lease Name or Unit Agreement Name Grizzell
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>860</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>22S</u> Range <u>37E</u> NMFM <u>Lea</u> County		8. Well No. 12
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3402' GR		9. Pool name or Wildcat Eunice; San Andres, Southwest

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<input type="checkbox"/> Perform Remedial Work	<input type="checkbox"/> Remedial Work
<input type="checkbox"/> Temporarily Abandon	<input checked="" type="checkbox"/> Commence Drilling Operations
<input type="checkbox"/> Pull or Alter Casing	<input type="checkbox"/> Casing Test and Cement Job
<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Other
<input type="checkbox"/> Change Plans	<input type="checkbox"/> Altering Casing
<input type="checkbox"/> Other	<input type="checkbox"/> Plug and Abandonment
	Surface & Production Casing


12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/7/01 MIRU Big Dog Rig # 5. Spud well @ 6:45 pm

4/9/01 Drilled 12-1/4" hole to 1160'. Ran 28 jts 8-5/8" 24# J-55 ST&C casing. Cemented w/ 325 sx 35/65 POZ "C" & 135 sx Class "C". Circulated 43 sx to pit

4/15/01 Drilled 7-7/8" hole to 4300'. Ran 96 jts 5-1/2" 17# J-55 LT&C casing. Cemented w/ 625 sx 35/65 POZ "C" & 350 sx Class "C". Circulated 112 sx to pit. Top of float collar @ 4209'. Top of float shoe @ 4298'. Released rig @ 11:00 am

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 	TITLE Sr. Engineering Technician	DATE 4/23/01
TYPE OR PRINT NAME Debra J. Anderson	TELEPHONE NO. 713-296-6338	
(This space for State Use)		
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		