Submit 3 Copies to Appropriate District Office		of New Mexico Natural Resources Depart	meı.	Form C-103 Revised 1-1-89	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERV	ATION DIVISION	WELL API I	NO. 30-025-36024	
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210		outh Pacheco e, NM 87505	5. Indicate	Type of Lease STATE 🛛 FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil	& Gas Lease No. B-3480	
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	S AND REPORTS ON WE POSALS TO DRILL OR TO D VOIR. USE "APPLICATION F FORM C-101) FOR SUCH PF	EEPEN OR PLUG BACK TO A OR PERMIT"	7. Lease N	Name or Unit Agreement Nar	ne
I. Type of Well: OIL GAS WELL WELL	OTHER			Cole State	
2. Name of Operator Zia Energy, Inc.			8. Well No. 15		
3. Address of Operator PO Box 2510, Hobbs, NM 88241				ne or Wildcat ice San Andres Southwest	
4. Well Location Unit Letter C 660 Feet Fi	rom The North Line	and <u>1780</u> Feet Fr	rom The West	Line	
Section 16 Towns		<u>37e NMPM</u> hether DF, RKB, RT, GR, etc.		County	
11. Check Apr	3408 GR	ature of Notice, Report, or Oth	, or Data		and the second
NOTICE OF INTENTION			JENT REPO	DRT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	\boxtimes	PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND CEMENT JO	ов 🛛		
OTHER:		OTHER:			
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	erations (Clearly state all pertir	nent details, and give pertinent date	es, including es	timated date of starting any prope	osed

11/18/02 RU Capstar. Spud 12 1/4".

11/20 TD 1134'. GIH with shoe, 1 jt and float collar, & 24 jts of 8 5/8" 24# casing with 8 centralizers. Set at 1127'. RU and cement with 450 sks of Light Premium Plus w/ .25 lbm Flocele and 3 lbm salt (accelerator) and tail in with 200 sks of Premium Plus with 2% Anhydrous Calcium Chloride (Accelerator). Plug down @ 11:30 am. Circ 176 sxs. SI 12 hrs.

11/21 Drill out shoe and test to 1000 psi. Drilling ahead with 7 7/8" bit.

11/25 TD 4217. RIH with float shoe, 1 jt 5 ½" and float collar and 94 jts of 15.5# J-55 casing. Punip (Jed) 475 sxs of Light Premium Plus with .25# flocele 5 lb/sx Salt followed by (tail) 500 sxs Premium Plus 50/50 Pozzwith .5 % Halad (low fluid loss), 1.5 % Potassium Chloride (Clay Control) and .25 lb/sx flocele. 20 bbls floo flush pressured up 2800 psi. RU to reciprocate and rotate. Did not break bridge. Shut down; Estimated TOC 450'; (60% fill). Cut off and nipple down. Release Rig.

hereby certify that the information above is true and complete to IGNATURE	TITLE	Engineer	date 11/26/02
YPE OR PRINT NAME Scott Nelson		505-393-2937	TELEPHONE NO.
This space for State Use)	ORIGINAL SIGNED B GARY W. WINK OC FIELD REPKESENT	Y FATIVE II/STAFE MANAGER	NOV 2 7 2002