

APPROVED

		B

JUL 11 1963

(SUBMIT IN TRIPLICATE)

UNITED STATES

J. L. GODE DEPARTMENT OF THE INTERIOR

ACTING DISTRICT ENGINEER GEOLOGICAL SURVEY

*Inspected location & found  
it okay for P.A.A.  
7-10-63 E.H.*

Land Office New MexicoLease No. LC-068911Unit B

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 27, 1962

Bondurant-Federal

Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 6NW 1/4 NE 1/4 Sec. 6  
(1/4 Sec. and Sec. No.)24S  
(Twp.)32E  
(Range)NMPM  
(Meridian)Wildcat

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3576.3 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was plugged and abandoned as follows:

Total depth 4796' with 8-5/8" casing at 300'

Spotted cement plugs as follows:

- 40 sacks at 4796' (bottom of hole)
- 40 sacks at 1300' (top of Salt)
- 40 sacks at 350' (Base of surface casing)

Identification marker and 10 sacks cement at surface.

Location to be cleared as soon as pits are dry.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Curtis HankamerAddress 214 Security National Bank Bldg.Roswell, New MexicoBy Max M. WilsonTitle Area Manager