

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-371-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
6800 Park Ten Blvd., San Antonio, TX 78213

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 1980' FEL
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE

NM-033503

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

USA Jennings

9. WELL NO.

3

10. FIELD OR WILDCAT NAME

Double X Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 14, T24S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. API NO.

30-025-08150

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
MINERALS MANAGEMENT
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RIH with 2 7/8" tubing and tagged bottom of open hole at approximately 4124' to verify depth.
2. Place 100' plug of cement at bottom of hole (4124' - 4024'). S.I. for 6 hours.
3. RIH w/tubing and tagged cement to verify location.
4. Place 100' plug of cement from 1450' - 1350' to isolate salt zone.
5. Place 100' plug of cement from 400' - 300' (50' below existing 8 5/8" csg to 50' within csg). S.I. for 6 hrs. RIH with tubing and tagged plug.
6. Placed 15 sx of cement for surface plug.
7. Installed surface plate & marker with proper identification.
8. Well PxA'd 11/5/82.

NOTE: 10 lb. brine placed between all plugs.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Robert G. Mathew TITLE Prod. Engr. Supv. DATE Dec. 16, 1982

APPROVED (This space for Federal or State office use)
(Orig. Sgd.) PETER W. CHESTER
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAR 1 1983
FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

MAR 3 1983

O.C.D.
HOBBS OFFICE