Form 9-881 a (Feb 1981)

(SUBMIT	IN	TRIPLICATE)
,		TAME DIGNIE

Budget Bureau 43-R308.5. Approval expires 12-31-52

Land Office

Lasso No. LC-066007

Unit 0

### UNITED STATES

## DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

# SUNDRY NOTICES AND REPORTS ON WELLS

TO KE-DRILL OK KEPAIR WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE  NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF ABANDONMENT

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sun-Federal
Well No. One is located 330 ft. from Si line and 2310 ft. from E line of sec. Five

SE/4 Sec. 5, Township 26 S, Range 32 E, N.M.P.M.

(Na Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft

#### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well drilled to total depth of 4703:.

We spotted 30 sacks of cement in the bottom and 10 sacks in the top of 8 5/8" casing, then installed regulation marker, per instructions from Mr. DuFont.

Well plugged and abandoned April 10, 1956.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company JOE S. HILL AND W. W. MEEKER
140 Jentral Building,
Address Midland, Texas

By ... Joe S. Hill