


APPROVED

Form 9-331a
(Feb. 1961)

MAR 16 1961

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.



E. W. STANDLEY
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

API 30-025-00271

Land Office Las Cruces

Lease No. 065876-A

Unit "I"

NOV 3

U.S. GEOLOGICAL SURVEY

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL

NOTICE OF INTENTION TO CHANGE PLANS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL

NOTICE OF INTENTION TO SHOOT OR ACIDIZE

NOTICE OF INTENTION TO PULL OR ALTER CASING

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF WATER SHUT-OFF

SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING

SUBSEQUENT REPORT OF ALTERING CASING

SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR

SUBSEQUENT REPORT OF ABANDONMENT

SUPPLEMENTARY WELL HISTORY

X

ILLEGIBLE

BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA:

October 31, 1959

Well No. 3 is located 1650 ft. from N line and 330 ft. from E line of sec. 24

NE¹/₄ of SE¹/₄, Sec. 24

Undesignated
(Field)

26S
(Twp.)

32E
(Range)

NMPM
(Meridian)

Lea

(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3156 ft. Inspected 3-14-61

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 4767: - Well drilled to 4705 - Cored 4706 to 4767 - Recovered 61: laminated sand - The top 4' had slight shows - Prepare to plug & abandon
10 sks at top of surface pipe & ground level
10 sks at 350' bottom of surface casing
15 sks at 695' top of Rustler
25 sks at 1090' bottom of Rustler
25 sks at 1710' Top of Delaware sand.

Hole full of mud laden material - Set 4" marker 4' above surface. Clean location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HILL & MEEKER

Address 519 Midland Savings &

Loan Bldg.

Midland, Texas

By

Title Production Clerk