

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL.
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. LEASE DESIGNATION AND SERIAL NO. LC-071985
2. NAME OF OPERATOR CONOCO INC.	3. INDIAN ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	4. UNIT AGREEMENT NAME North El Mar
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface: Unit A	5. FARM OR LEASE NAME North El Mar Unit
14. PERMIT NO. 660' FNL & 660' FEL	6. WELL NO. 5
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 30-025-08272	7. FIELD AND POOL, OR WILDCAT El Mar Delaware
	8. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25-26S-32E
	9. COUNTY OR PARISH 10. STATE Lea NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLAN ☐
(Other) **temporary abandon** ☒


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and completion of this work.) If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)

- ① MIRU. POOH w/ production equip. Make bit & scraper run to perfs.
- ② GTH w/ CIBP & pkr to $\pm 4620'$. Set CIBP @ $\pm 4620'$. Test CIBP to 1000 psi. Test backside to 600 psi.
- ③ Rel pkr & POOH. Circ. hole full of 10.0 ppg brine. Rig down.



18. I hereby certify that the foregoing is true and correct

SIGNED Walter J. Finney TITLE Administrative Supervisor

DATE 12-17-86

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY: _____

TITLE _____

DATE 12-18-86

*See instructions on Reverse Side



RECEIVED
DEC 22 1986
OCD
HOBBS OFFICE