

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
300 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-08491
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-5898-1
7. Lease Name or Unit Agreement Name	Bell Lake Unit 1
8. Well No.	4
9. Pool name or Wildcat	Bell Lake Morrow, South

Section	6	Township	24S	Range	34E	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)						3615 DF		

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐
Name of Operator
Kaiser-Francis Oil Company
Address of Operator
P. O. Box 21468, Tulsa, OK 74121-1468

Well Location
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 6 Township 24S Range 34E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3615 DF

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Add'l perms in Morrow formation <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TOOH w/tbg & packer.
2. RU WL & set cmt retainer @ 13220'.
3. TIH w/2 7/8" tbg & stinger. Sting into retainer.
4. Pump 100 sxs cmt thru retainer. POO retainer & dump 2 sxs cmt on top.
5. TOH w/tbg & stinger.
6. TIH w/Arrow MX-1 packer & 2 7/8" tbg.. Set packer @ 13050'.
7. RU WL. Perf Morrow sand @ 13110'-13190' o.a. using a 2 1/8" strip gun.
8. Flow test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlotte Van Valkenburg TITLE Technical Coordinator DATE 11/5/99
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: